### **ENVIRONMENTAL**ASSESSMENT

CITY OF HARTFORD

DEPARTMENT OF DEVELOPMENT SERVICES-HOUSING AND PROPERTY MANAGEMENT DIVISION 2021-2022





### **DEPARTMENT OF DEVELOPMENT SERVICES-HOUSING AND PROPERTY MANAGEMENT DIVISION**

### 2021-2022

PROJEC	T NAME:	1154-1170 Albany Avenue – We	eaver Building	g				
PROJEC	T LOCATION:	1154-1170 Albany Avenue Hartford, CT						
PROJEC	T SPONSOR:	Ace Developments						
PROJEC	T CONTACT:	Ace Andaleeb – 203-763-9699						
ESTIMA	TED TOTAL PROJECT COST:	The total cost for the project is project will consist of:  • \$ 500,000 – City of Hartford			_			
		• \$ 380,000 – Developer's fur	nding					
RESPON	ISIBLE ENTITY:		City of Hartford Management and Budget Department, Office of Central Grants Admn 550 Main Street, Room 302, Hartford, CT 06103					
CERTIFY	YING OFFICER:	Lionel Rigler, Environmental Rev	view Project	Manager (8	60) 757-9277			
List all n	ns must be included in project con	responsible entity to eliminate or m tracts or other relevant documents						
ENVIRO	NMENTAL FINDING: [58.40(g)]							
	Categorical exclusion is made in ac	cordance with § 50.20.						
$\overline{\checkmark}$	Environmental Assessment and a F	inding of No Significant Impact (FON	ISI) is made in	accordance	with § 50.33.			
	Environmental Assessment and a F is required in accordance with §§ 5	inding of Significant Impact is made, 0.33(d) and 50.41.	and an Enviro	onmental Imp	pact Statement			
THIS EN	NVIRONMENTAL <b>A</b> SSESSMENT WAS	PREPARED BY:		, .	1 0 . 1			
Name	: Lionel Rigler		Signature:_	Lionel	Rigler			
Title:	Environmental Review Project Ma City of Hartford Management and Budget Departn Office of Central Grants Administr	nent	Date: Dec					
APPROV	/ED BY:		(	van (	Johnson			
Name	Evan Johnson		Signature:_		<u>/</u>			
Title:	Director, Office of Central Grants	Administration	Date:		12/3/2021			

12/3/2021

### DEPARTMENT OF DEVELOPMENT SERVICES-HOUSING AND PROPERTY MANAGEMENT DIVISION 2021-2022

### **PART ONE: PROJECT DESCRIPTION AND ACTIVITIES**

**STATEMENT OF PURPOSE AND NEED FOR THE PROPOSAL:** [40 CFR 1508.9(B)]

To rehabilitate a blighted and underdeveloped property in Hartford's Upper Albany neighborhood.

DESCRIPTION OF THE PROPOSAL: INCLUDE ALL CONTEMPLATED ACTIONS THAT ARE EITHER GEOGRAPHICALLY OR FUNCTIONALLY A COMPOSITE PART OF THE PROJECT, REGARDLESS OF THE SOURCE OF FUNDING. [24 CFR 58.32, 40 CFR 1508.25]

The project located at 1154-1170 Albany Avenue, the Weaver Building, within the Upper Albany neighborhood of the City of Hartford, CT. The project entails rehabilitation and improvements to 18 vacant apartments that are currently not habitable. This includes repairs and or replacements of kitchen cabinets and countertops, appliances, bathroom vanities and plumbing, electrical wiring and circuit breakers, fire alarm system, heating systems, doors, windows, trim and painting. Additionally, exterior repairs and improvements, including façade improvements, masonry repairs, repointing and cleaning, paving, landscaping and roofing.

Construction is anticipated to commence in January 2022 with a construction duration of approximately 3 months.

EXISTING CONDITIONS AND TRENDS: DESCRIBE THE EXISTING CONDITIONS OF THE PROJECT AREA AND ITS SURROUNDINGS, AND TRENDS LIKELY TO CONTINUE IN THE ABSENCE OF THE PROJECT. [24 CFR 58.40(a)]

In the absence of this project, the existing parcel would likely remain blighted and under-developed for some time.

### CITY OF HARTFORD DEPARTMENT OF DEVELOPMENT SERVICES-HOUSING AND PROPERTY MANAGEMENT DIVISION 2021-2022

### **PART TWO: ENVIRONMENTAL REVIEW**

### A) STATUTORY CHECKLIST

	Ħ				>*	_	
Area of Statutory or Regulatory Compliance	Not Applicable to This Project	Consultation Required*	Review Required*	Permits Required*	Determination of consistency Approvals, Permits obtained*	Conditions and/or Mitigation Actions Required	Provide compliance documentation. Additional material may be attached.
Historic Properties [36 CFR 800]	<b>✓</b>						The State Historic Preservation Office reviewed the information submitted for the above- named property pursuant to the provisions of Section 106 of the National Historic Preservation Act of 1966 and Connecticut Environmental Policy Act.
							They stated:  "The property located at 1154-1170 Albany Avenue, the Weaver Building (1926), potentially eligible for listing on the National Register of Historic Places (NR) as contributing resource to the adjacent Upper Albany Historic District (NR# 86003383).
							Your proposal includes rehabilitation of the Subject Property, including replacement of existing storefronts, repointing of masonry, interior rehabilitation, and repairs to cast stone trim elements.
							In accordance with the Secretary of the Interior's Standards for the Treatment of Historic Properties, new ornamental trim should be differentiated from existing, historic trim, so as not to give a false sense of historicity. Note that care should be taken in the cleaning, repointing, and repair of historic masonry materials.
							Regarding the repair to cast stone elements, please refer to the National Park Service's Preservation Brief# 42: The Maintenance, Repair and Replacement of Historic Cast Stone. Regarding repointing, replacement mortar should match the original in color, strength, porosity, and tooling profile; please refer to Preservation Brief #2: Repointing Mortar Joints in Historic Masonry Buildings, for appropriate materials and techniques. Lastly, cleaning should be accomplished using the gentlest means possible; please refer to Preservation Brief #1: Cleaning and Water- Repellent Treatments for Historic Masonry Buildings, and Preservation Brief #6: Dangers of Abrasive Cleaning to Historic Buildings, for further information on appropriate techniques.
							Though not explicitly enumerated within the scope of work, the Project Proponent expressed a desire to

### **DEPARTMENT OF DEVELOPMENT SERVICES-HOUSING AND PROPERTY MANAGEMENT DIVISION**

			remove accumulated graffiti on the Subject Property's exterior. Please refer to Preservation Brief #38: Removing Graffiti from Historic Masonry for appropriate materials and techniques.  Contingent on the undertaking following the recommendations above, SHPO has determined that the scope of work will constitute no adverse effects to historic resources. Should the scope of work change, this office should be contacted for additional consultation.  (Catherine Labadia, Deputy State Historic Preservation Officer, SHP) Nov 26, 2021
Floodplain Management [24CFR55, EO 11988]	<b>✓</b>		Project site is not located within the 100- or 500-year flood zone and does not require flood insurance. (indicated on Property Detail Map included in Environmental Review Record)
Wetlands Protection [EO 11990]	<b>✓</b>		Project not in wetland areas defined by City 1987 Designated Inlands, Wetlands, and Watercourses Map. (included in Environmental Review Record)
Coastal Zone Management [Sec. 307(c), (d)]	<b>✓</b>		Hartford is not located in a coastal zone. CT Map. (included in Environmental Review Record)
Water Quality– Aquifers [40 CFR 149]	<b>✓</b>		Hartford is not located on a sole source aquifer. State of CT Aquifer Map. (included in Environmental Review Record)
Endangered Species [50 CFR 402]	<b>✓</b>		None in area, per Natural Diversity Database Digital Data. (indicated on Property Detail Map included in Environmental Review Record)
Wild & Scenic Rivers [Sections 7 (b), (c)]	<b>✓</b>		There are no designated wild and scenic rivers within the City of Hartford. (HUD Tidbits of the Environment #06-017 dated 10/6/05)

### DEPARTMENT OF DEVELOPMENT SERVICES-HOUSING AND PROPERTY MANAGEMENT DIVISION

Area of Statutory or Regulatory Compliance	Not Applicable to This Project	Consultation Required*	Review Required*	Permits Required*	Determination of consistency Approvals, Permits obtained*	Conditions and/or Mitigation Actions Required	Provide compliance documentation. Additional material may be attached.
							For each listed statute, executive order or regulation, record the determinations made. Note reviews and consultations completed as well as any applicable permits or approvals obtained. Attach evidence that all required actions have been taken. Categorically Excluded Activities: Determine whether projects are: exempt, need mitigation, need an environmental assessment (EA).
Air Quality [Clean Air Act, Sections 176 (c) and (d), and 40 CFR 6, 51, 93]	✓						No industrial operation or power station is located in the project area. The project will also not create a large number of dwelling units that might generate a high volume of vehicular traffic i.e. 1,000 or more vehicles.  (http://www.hud.gov/offices/cpd/energyenviron/environment/compliance/forms/trngmanual/chapt2compliance.cfm)
Farmlands Protection [7 CFR 658]	<b>√</b>						Project is on previously developed land, and will have no impact on prime or unique farmland or other farmland of state or local importance. (indicated on Property Detail Map included in Environmental Review Record)
Manmade Hazards Thermal/Explosive [24 CFR 51 C]	<b>✓</b>						Project is an Acceptable Safe Distance from thermal/explosive hazards nor project will expose neither people nor buildings to such hazards.
Noise [24 CFR 51 B]	<b>√</b>						The noise to be generated by construction equipment between 7AM-6PM on weekdays and Saturdays is considered exempt from ordinance. (Hartford Municipal Code, Ch. 23, Noise, Sec. 23-3(e)) The project site is also fully surrounded by existing urban and commercial uses. (area knowledge)
Airport Clear Zones [24 CFR 51 D]	<b>✓</b>						There are no commercial service airports in the area as designated by National Plan of Integrated Airport Systems, prepared by the FAA. (revised HUD Tidbit #06-021 dated 7/21/06)

Area of Statutory or Regulatory Compliance	Not Applicable to This Project	Consultation Required*	Review Required*	Permits Required*	Determination of consistency Approvals, Permits obtained*	Conditions and/or Mitigation Actions Required	Provide compliance documentation. Additional material may be attached.
Toxic Sites [24 CFR 58.5(i)(2)]							Phase 2 report conclusions  1. Releases to the environment (defined as a detection of a substance above laboratory minimum detection limit) have been identified by detection of contaminants at levels above laboratory minimum detection limits in sub-slab soil in the basement of the Subject Site. One of the sampling locations was found to contain levels of contaminants above CT DEEP criteria however, the criteria do not apply to this area as per CT regulation 22a-133k-1(a)(32) Direct Exposure Criteria Exemption – Inaccessible Soil is defined as polluted soil which is: (D)(i) "beneath an existing building."  The releases are summarized below.  a. AOC-1; Soil collected from boring SSB1, beneath the concrete slab, contained levels of ETPH above the CT DEEPs Remediation Standard Regulations for Residential Direct Exposure Criteria. The soil also contained detectable levels of volatile organic compounds and semi-volatile organic compounds above laboratory detection limits but below all applicable CT DEEP regulations. Soil Collected from boring SSB3 contained levels of ETPH, VOCs, and SVOCs above laboratory detection limits but below all applicable CT DEEP regulations.  b. AOC-2; Soil collected from boring SSB2, adjacent to the sump-pit, contained levels of ETPH, VOCs, and SVOCs above laboratory detection limits but below all applicable CT DEEP regulations.  2. No evidence of a buried storage tank or a release to the environmental have been identified in AOC-3.  3. No impact to ground water has been identified.  RECOMMENDATIONS  1. Patch all broken areas of concrete floor in basement to prevent any direct human contact with soil below.  Phase II Environmental Site Assessment, 1154-1170 Albany Avenue, Prepared by: Big East Environmental, August, 2021

			Hazmat Report Conclusions
			No asbestos containing materials have been identified during the limited non-destructive asbestos inspection of the residential units. Suspect-asbestos containing materials have been visually identified during the limited visual survey of the commercial units. These items shall be considered ACM until laboratory analysis is performed.
			No Lead-based paint has been identified on site during the limited LBP survey of the residential units. Painted surfaces in damaged condition have been identified in the commercial units. These surfaces should be managed in place with paint stabilization techniques.
			No known PCB containing materials have been identified during the course of the presumptive survey. Due to the buildings age, PCB containing caulk, glazing, paint, and tars can exist in the window, door, and roofing systems.
			No evidence of Urea Formaldehyde Foam Insulation (UFFI) has been identified during the nondestructive visual survey.
			Radon testing the basement for the Subject Site has found levels of radon below the US EPA action level.
			Limited Hazmat Survey Report, 1154-1170 Albany Avenue, Prepared by: Big East Environmental, August, 2021
Environmental Justice [EO 12898]	<b>√</b>		The rehabilitation and improvements to eighteen (18) apartments does not have the potential for new or continued disproportionately high and adverse human health and environmental effects on minority or low-income populations, and is not likely to raise environmental justice issues.
Flood Insurance - 58.6(a)	<b>✓</b>		Project site is not located within the 100 or 500-year flood zone and does not require flood insurance. (See Property Detail Map included in Environmental Review Record)
Coastal Barriers - 58.6(b)	$\checkmark$		Hartford is not located in a coastal zone. (CT map included in Environmental Review Record)
Airport Clear Zone Notification - 58.6(c)	✓		Project is not located within 2500 feet of runway of a designated FAA facility. (revised HUD Tidbit #06-021, dated 7/21/06)
Water Quality	<b>√</b>		Groundwater is classified as GB. Class GB groundwater is designated for industrial process water and cooling waters and baseflow for hydraulically-connected water bodies and is presumed not suitable for human consumption without treatment. The project site is served by municipal water and sewer through the Metropolitan

### **DEPARTMENT OF DEVELOPMENT SERVICES-HOUSING AND PROPERTY MANAGEMENT DIVISION**

							District Commission. WSP USA, 4 Research Drive, Suite 204, Shelton, CT, May 2019. Phase I Environmental Site Assessment Section 3.5 included in Environmental Review Record)
Solid Waste Disposal	<b>√</b>						The City of Hartford Department of Public Works handles solid waste disposal. Demolition debris must follow disposal pursuant to State and Local guidelines.  (www.hartford.gov/Public Works/Waste & Recycling)
Area of Statutory or Regulatory Compliance	Not Applicable to This Project	Consultation Required*	Review Required*	Permits Required*	Determination of consistency Approvals, Permits obtained*	Conditions and/or Mitigation Actions Required	Provide compliance documentation. Additional material may be attached.
Fish and Wildlife	>						Project site occupies land already developed for residential purposes. No endangered species in area, as per Natural Diversity Database Digital Data. (indicated on Property Detail Map included in Environmental Review Record)
Building permits				✓			Must be obtained prior to start of work.  (http://www.Hartford.gov/Development/lic-inspect/ lic-build-permitapp.htm)
Asbestos Abatement						✓	"No asbestos containing materials have been identified during the limited non-destructive asbestos inspection of the residential units. Suspect-asbestos containing materials have been visually identified during the limited visual survey of the commercial units. These items shall be considered ACM until laboratory analysis is performed.  Limited Hazmat Survey Report, 1154-1170 Albany Avenue, Prepared by: Big East Environmental, August, 2021  If encountered during project activities, the contractor is responsible to handle and dispose of asbestos according to State and Federal laws, and to notify the Div. of Grants
							Management of any change in the project scope.  http://www.dph.state.ct.us/BRS/asbestos/40CFR763WHOLE.p  df
LBP Abatement						<b>✓</b>	"No Lead-based paint has been identified on site during the limited LBP survey of the residential units. Painted surfaces in damaged condition have been identified in the commercial units. These surfaces should be managed in place with paint stabilization techniques."  Limited Hazmat Survey Report, 1154-1170 Albany Avenue, Prepared by: Big East Environmental, August, 2021  If encountered during project activities, the contractor is responsible to handle and dispose of lead-based paint according to State and Federal laws, and to notify the Division of Grants Management of any change in the project scope.  www.dph.state.ct.us/BRS/Lead/RegsandStatutes/lead_regulations.htm

### **B) ENVIRONMENTAL ASSESSMENT**

[Environmental Review Guide HUD CPD 782, 24 CFR 58.40; Ref. 40 CFR 1508.8 &1508.27] Evaluate the significance of the effects of the proposal on the character, features and resources of the project area. Enter relevant base data and verifiable source documentation to support the finding. Then enter the appropriate impact code from the following list to make a determination of impact. Note names, dates of contact, telephone numbers and page references. Attach additional material as appropriate. Note conditions or mitigation measures required.

Impact Codes: (1) - No impact anticipated; (2) - Potentially beneficial;	(4) - Requi	Potentially adverse; Requires mitigation; Requires project modification					
LAND DEVELOPMENT	CODE	Source or Documentation					
Conformance with Comprehensive Plans and Zoning	2	<u>Planning and Zoning Review</u> – The project will be presented to the Planning and Zoning Commission. The Planning and Zoning Commission must approve the project before it can proceed.					
Compatibility and Urban Impact	2	The project will be presented to the Planning and Zoning Commission. No determination yet from the Planning and Zoning Commission. The Planning and Zoning Commission must approve the project before it can proceed.					
Slope	1	No comment on the slope					
Erosion	1	Construction activities shall be consistent with the Connecticut General Permit for the Discharge of Stormwater and Dewater Wastewater Associated with Construction Activities and will implement appropriate erosion and sediment controls. (www.cicacenter.org/pdf/ctpermit.pdf)					
Soil Suitability	1	Nothing significant about the soil suitability was noted in the Preliminary Environmental Report.					
Hazards and Nuisances including Site Safety	1	No known PCB containing materials have been identified during the course of the presumptive survey. Due to the buildings age, PCB containing caulk, glazing, paint, and tars can exist in the window, door, and roofing systems.  No evidence of Urea Formaldehyde Foam Insulation (UFFI) has been identified during the nondestructive visual survey.  Radon testing the basement for the Subject Site has found levels of radon below the US EPA action level.  Limited Hazmat Survey Report, 1154-1170 Albany Avenue, Prepared by: Big East Environmental, August, 2021					
Energy Consumption	1	The project must meet, at a minimum, City of Hartford and State of Connecticut basic building codes, any existing rehabilitation standards, zoning ordinances, HUD Housing Quality Standards, and the Model Energy Code. (www.hartford.gov/housing/programs/HOME-program/home-program07-10-04.htm; www. Hartford.gov/Development/planning/Docs/regs_zoning.pdf).					

### **DEPARTMENT OF DEVELOPMENT SERVICES-HOUSING AND PROPERTY MANAGEMENT DIVISION**

Impact Codes: (1) - No impact anticipated; (2) - Potentially beneficial;	(4) - Requi	tially adverse; res mitigation; res project modification
Noise-Contribution to Community Noise Levels	1	The noise to be generated by construction equipment between 7AM-6PM on weekdays and Saturdays is considered exempt from ordinance (Hartford Municipal Code, Chapter 23, Noise, Section 23-3(e)). The project site is also fully surrounded by existing urban and commercial uses, and when occupied is anticipated to have no impact on community noise levels.
Air Quality-Effects of Ambient Air Quality on Project and Contribution to Community Pollution Levels	1	There are no nearby sources for localized pollution (industry, dump, power stations) and the project consisting of rehabilitation in a historic mixed-use building will not contribute significantly to the extent of existing pollution (smog, dust, odors, smoke) in the existing residential and commercial district.
Environmental Design Visual Quality- Coherence, Diversity, Compatible Use and Scale	1	"The property located at 1154-1170 Albany Avenue, the Weaver Building (1926), potentially eligible for listing on the National Register of Historic Places (NR) as contributing resource to the adjacent Upper Albany Historic District (NR# 86003383).
Scale		Your proposal includes rehabilitation of the Subject Property, including replacement of existing storefronts, repointing of masonry, interior rehabilitation, and repairs to cast stone trim elements.
		In accordance with the Secretary of the Interior's Standards for the Treatment of Historic Properties, new ornamental trim should be differentiated from existing, historic trim, so as not to give a false sense of historicity. Note that care should be taken in the cleaning, repointing, and repair of historic masonry materials.
		Regarding the repair to cast stone elements, please refer to the National Park Service's Preservation Brief# 42: The Maintenance, Repair and Replacement of Historic Cast Stone. Regarding repointing, replacement mortar should match the original in color, strength, porosity, and tooling profile; please refer to Preservation Brief #2: Repointing Mortar Joints in Historic Masonry Buildings, for appropriate materials and techniques. Lastly, cleaning should be accomplished using the gentlest means possible; please refer to Preservation Brief #1: Cleaning and Water-Repellent Treatments for Historic Masonry Buildings, and Preservation Brief #6: Dangers of Abrasive Cleaning to Historic Buildings, for further information on appropriate techniques.
		Though not explicitly enumerated within the scope of work, the Project Proponent expressed a desire to remove accumulated graffiti on the Subject Property's exterior. Please refer to Preservation Brief #38: Removing Graffiti from Historic Masonry for appropriate materials and techniques.
		Contingent on the undertaking following the recommendations above, SHPO has determined that the scope of work will constitute <u>no adverse effects</u> to historic resources. Should the scope of work change, this office should be contacted for additional consultation.
		(Catherine Labadia, Deputy State Historic Preservation Officer, SHP) Nov 26, 2021
Demographic Character Changes	2	The properties are zoned MS-1 which this proposal complies with standard.
Displacement	1	There will be no displacement, as the project will is on currently undeveloped property.

### **DEPARTMENT OF DEVELOPMENT SERVICES-HOUSING AND PROPERTY MANAGEMENT DIVISION**

Impact Codes: (1) - No impact anticipated; (2) - Potentially beneficial;	<ul><li>(3) - Potentially adverse;</li><li>(4) - Requires mitigation;</li><li>(5) - Requires project modification</li></ul>					
SOCIOECONOMIC	CODE	Source or Documentation				
Employment and Income Patterns	2	The project will most likely support the local construction industry on a short term basis. The project site is located in Census Tract 5014; its population contains <b>69.2%</b> low- and moderate- income families. (2010-15 ACS Census)				
Educational Facilities	1	The addition of eighteen apartments is not anticipated to impact the demand for educational services.				
Commercial Facilities	1	In the mile surrounding the project site, there are several commercial entities such as banks, salons, medical offices, markets, pharmacies and eateries.				
COMMUNITY FACILITIES AND SERVICES	CODE	Source or Documentation				
Health Care	1	Based on the project description of the rehabilitation of 18 apartments in a historic mixed-use building, no adverse impact is anticipated to the demand on health services. St. Francis Hospital is a full-service health care facilities located within 1 mile of the project site.				
COMMUNITY FACILITIES AND SERVICES	CODE	Source or Documentation				
Social Services	1	Based on the project description of production of 18 apartment units, no adverse impact is anticipated to the demand on social services. In addition to services offered by the City's Health and Human Services Department, there are several and varied social service providers within close proximity of the project site.				
Solid Waste	1	Site is included in the City's weekly Dept. of Public Works pickup schedule. ( <a href="https://www.hartford.gov/Public_Works/Waste_&amp;_Recycling/cllctnad406.pdf">www.hartford.gov/Public_Works/Waste_&amp;_Recycling/cllctnad406.pdf</a> ) Regulations are detailed in the City's Waste and Recycling Guidelines, Rules, and Regulations 2006 Edition. ( <a href="https://www.hartford.gov/Public_Works/Guide/guidelines.pdf">https://www.hartford.gov/Public_Works/Guide/guidelines.pdf</a> )				
Waste Water	1	The City's wastewater is handled by the Metropolitan District Commission sewage plant service. (http://www.themdc.com)				
Storm Water	1	Based on the site's urban setting, stormwater likely discharges to the municipal storm sewers. The project developer will ensure that facilities shall be connected to MDC storm water disposal service as other facilities in the area. Storm water is channeled to MDC storm drains, either through direct rain leaders or appropriate site grading. (http://www.themdc.com)				
Water Supply	1	The project site is served by municipal water and sewer through the Metropolitan District Commission. (http://www.themdc.com) No change is anticipated as the project site was once occupied by residences.				
Public Safety - Police	1	911 services are available throughout Hartford for public safety emergencies. Hartford Police Department headquarters, located at 253 High Street, is approximately 1.0 miles east of the project site.				

### **DEPARTMENT OF DEVELOPMENT SERVICES-HOUSING AND PROPERTY MANAGEMENT DIVISION**

Impact Codes: (1) - No impact anticipated; (2) - Potentially beneficial;	(4) - Requi	tially adverse; res mitigation; res project modification
- Fire	1	911 service is available throughout Hartford for fire emergencies and the Fire Department is the first responder for medical emergencies. District 1, located at 275 Pearl Street, is approximately 1.5 miles from the project site.
- Emergency Medical	1	911 service is available throughout Hartford for fire emergencies and the Fire Department is the first responder for medical emergencies. District 1, located at 275 Pearl Street, is approximately 1.5 miles from the project site.
Open Space and Recreation -Open Space	1	Keney Park, located less than 1 mile from the project site, features areas for baseball, soccer, picnic areas, playgrounds, recreation center and outdoor swimming pool.
-Recreation	1	Keney Park, located less than 1 mile from the project site, features areas for baseball, basketball, soccer, picnic areas, playgrounds, recreation center and outdoor swimming pools.
COMMUNITY FACILITIES AND SERVICES	CODE	Source or Documentation
-Cultural Facilities	1	Project site is in walking distance/local bus to a variety of cultural facilities such as Mark Twain House; Real Art Ways; Wadsworth Atheneum; Hartford Stage Company; XL Center; Theatreworks, Hartford Public Library; Bushnell Auditorium; and many worship centers. (area knowledge/field observation)
Transportation	1	The project is unlikely to result in significantly more traffic than currently exists or historically existed in the project area. The site is served by Connecticut Transit's 50-54, 56, 58, 901, 902 and 46 bus routes on Albany Avenue. (cttransit.com) The Amtrak train and multi-carrier bus station are located approximately 1.7 mile from the project site. (MapQuest)
NATURAL FEATURES	CODE	Source or Documentation
Water Resources	1	Construction activities shall be consistent with the CT General Permit for the Discharge of Stormwater and Dewater Wastewater Associated with Construction Activities and will implement appropriate erosion and sediment controls (www.cicacenter.org/pdf/ctpermit.pdf).
Surface Water	1	The nearest watercourse to the site is the Park River approximately 2,700 feet west of the subject site. The classification is C/B, which represents a surface water body that is not currently meeting one or more class B water criteria as a result of one or more sources of pollution. (Phase I, Section 2.2.1)
Unique Natural Features and Agricultural Lands	1	Project site not located in areas of farmland or other such importance. (indicated on Property Neighborhood Map included in Environmental Review Record)

### **DEPARTMENT OF DEVELOPMENT SERVICES-HOUSING AND PROPERTY MANAGEMENT DIVISION**

Impact Codes: (1) - No impact anticipated; (2) - Potentially beneficial;	<ul><li>(3) - Potentially adverse;</li><li>(4) - Requires mitigation;</li><li>(5) - Requires project modification</li></ul>						
Vegetation and Wildlife	1	Project site is currently developed as urban land, and is not in the vicinity of any endangered species. (indicated on Property Detail Map included in Environmental Review Record)					
OTHER FACTORS	CODE	Source or Documentation					
Flood Disaster Protection Act [Flood Insurance] [§58.6(a)]	1	Project site is not located on the 100- or 500- year flood zone, and does not require flood insurance. (indicated on Property Detail Map included in Environmental Review Record)					
Coastal Barrier Resources Act- Coastal Barrier Improvement Act [§58.6(c)]	1	Hartford is not a coastal city. (Connecticut map, included in Environmental Review Record)					
Airport Runway Clear Zone or Clear Zone Disclosure [§58.6(d)]	1	Project is not located within 2500 feet of runway of a designated FAA facility. (revised HUD Tidbit #06-021 dated 7/21/06).					

### DEPARTMENT OF DEVELOPMENT SERVICES-HOUSING AND PROPERTY MANAGEMENT DIVISION 2021-2022

### **PART III: SUMMARY OF FINDINGS AND CONCLUSIONS**

### **Alternatives to the Proposed Actions**

No significant and unavoidable adverse impacts were identified for the proposed project. Therefore, project alternatives or modifications have not been considered.

### No Action Alternative [24 CFR 58.40(e)]

The No Action Alternative: This alternative considers the impact of no change at the site; the lots at the project site would remain as a blighted property, which would continue to negatively impact aesthetics, socioeconomic conditions, and public health and safety as compared to the proposed project.

The No Action alternative would result in the loss of 18 apartments.

### **Attached Studies or Summaries**

- 1) Phase I Environmental Site Assessment for 1154-1170 Albany Avenue, Hartford, CT; Big East Environmental (August 2021)
- Phase II Environmental Site Assessment for 1154-1170 Albany Avenue, Hartford, CT; Big East Environmental (August 2021)
- 3) Limited Hazmat Survey Report 1154-1170 Albany Avenue, Hartford, CT; Big East Environmental (August 2021)
- 4) SHPO letter November 26, 2021

### List of Sources, Agencies and Persons Consulted [40 CFR 1508.9(b)]

- City of Hartford Planning and Zoning Regulations (http://www.hartford.gov/images/Planning/POSTING\_Hartford\_Zoning\_Final\_2016.01.22\_SECURE.pdf)
- **2)** City of Hartford 2016-2020 Consolidated Plan (http://www.hartford.gov/images/Grants/WEB-FINAL%20CONPLAN%20062514.pdf)
- **3)** CT Transit Bus Schedule (www.cttransit.com)
- 4) United States EPA Website (www.epa.gov)
- **5)** City of Hartford Website (www.hartford.gov)
- 6) Hartford Public Schools Website (www.hartfordschools.org)
- **7)** Metropolitan District Commission Website (www.themdc.com)
- 8) Google Maps
- 9) ESRI/ArcMap
- **10)** Centers for Disease Control/NIOSH Website (www.cdc.gov/niosh/)
- **11)** CT Dept. of Environmental Protection (www.ct.gov/dep/)
- 12) Riverfront Recapture website (www.riverfront.org)
- 13) Area Knowledge/Field Observation by Environmental Review Officer

### **Additional Notes:**

This Environmental Assessment was prepared based on the Phase I Environmental Site Assessment and all related documents submitted to the Department of Development Services Housing and Property Division.

**Ace Developments** shall provide the Department of Development Services Department, Division of Housing and Property and the Department of Management and Budget, Office of Central Grants with documentation of the remedial action taken, contaminants found in the process, and any additional information that may change the scope of the work recommended on the aforementioned environmental report(s).

**Ace Developments** shall be aware that this environmental assessment is subject to revision, should conditions change.



November 26, 2021

Mr. Brian Mathews City of Hartford 260 Constitution Plaza, 1st Floor Hartford, CT 06103-1822

Subject: 1154-1170 Albany Avenue

Hartford, CT ENV-22-0403

Dear Mr. Mathews:

The State Historic Preservation Office has reviewed the information submitted for the above-named property pursuant to the provisions of Section 106 of the National Historic Preservation Act of 1966 and Connecticut Environmental Policy Act.

The property located at 1154-1170 Albany Avenue, the Weaver Building (1926), potentially eligible for listing on the National Register of Historic Places (NR) as contributing resource to the adjacent Upper Albany Historic District (NR# 86003383).

Your proposal includes rehabilitation of the Subject Property, including replacement of existing storefronts, repointing of masonry, interior rehabilitation, and repairs to cast stone trim elements.

In accordance with the Secretary of the Interior's Standards for the Treatment of Hisotirc Properties, new ornamental trim should be differentiated from existing, historic trim, so as not to give a false sense of historicity. Note that care should be taken in the cleaning, repointing, and repair of historic masonry materials. Regarding the repair to cast stone elements, please refer to the National Park Service's Preservation Brief# 42: The Maintenance, Repair and Replacement of Historic Cast Stone. Regarding repointing, replacement mortar should match the original in color, strength, porosity, and tooling profile; please refer to Preservation Brief #2: Repointing Mortar Joints in Historic Masonry Buildings, for appropriate materials and techniques. Lastly, cleaning should be accomplished using the gentlest means possible; please refer to Preservation Brief #1: Cleaning and Water-Repellent Treatments for Historic Masonry Buildings, and Preservation Brief #6: Dangers of Abrasive Cleaning to Historic Buildings, for further information on appropriate techniques.



Though not explicitly enumerated within the scope of work, the Project Proponent expressed a desire to remove accumulated graffiti on the Subject Property's exterior. Please refer to Preservation Brief #38: *Removing Graffiti from Historic Masonry* for appropriate materials and techniques.


Contingent on the undertaking following the recommendations above, SHPO has determined that the scope of work will constitute <u>no adverse effects</u> to historic resources. Should the scope of work change, this office should be contacted for additional consultation.

The State Historic Preservation Office appreciates the opportunity to review and comment upon this project. These comments are provided in accordance with the Connecticut Environmental Policy Act and Section 106 of the National Historic Preservation Act. For further information please contact Marena Wisniewski, Environmental Reviewer, at (860) 500-2357 or marena.wisniewski@ct.gov.


Sincerely,


Catherine Labadia


Deputy State Historic Preservation Officer



1020000000 Feet









### **SECTION 106 REVIEW: 1154 ALBANY AVUENUE**

### **Property Details**

Located in Historic District: No Name of Historic District: N/A


Development Services Historic Preservation Address: N/A Program: Section 8 - Housing Choice Voucher Program


Description of Work: Exterior work: N/A

Interior work: Project Based Vouchers











êdem pind €



Ca.



"Hazardous Waste Facilities" as defined by Section 22a-134f of the Connecticut General Statutes

### **TOWN OF: HARTFORD**

<u>Post</u> Remedial

Contract of the Contract of th	<u>Name</u>		
	Address		
	Site Definition		
	Started	Investigation	
	Started	Remediation	
	<u>Started</u>	Monitoring	Wemenin
	Completed	Remediation	
	ELUR		

ELUR Type

2	243 Farmington Ave.	214 Main Street Assoc.	175 Mather Street	170 Weston St.	151 Earl Street	1409 Park Street	138 Jefferson Street	120 Oxford Street	1115 Albany Ave	100 Prospect Street	Capitol Dist Cogeneratio	Hartford Unlin Gordon Jones		
38 - 40 Hungerford Street	lton	reet Assoc.	Street	St.	eet	treet	n Street	Street	/Ave	d Street	Capitol District Energy Center Cogeneration Associates	Hartford Unlimited Enterprises, Gordon Jones		
38 - 40 Hungerford Street	243 Farmington Ave.	214 Main Street	175 Mather Street	170 Weston St.	151 Earl Street	1409 Park Street, 31 Pope Park Highway	138 Jefferson Street	120 Oxford Street	1115 Albany Ave	100 Prospect Street	410 Capitol Avenue- 490 Capitol Avenue	450 Holmstead Ave	2 Mortson Road	1950 Main Street
Leaking Underground Storage Tanks – Completed	Leaking Underground Storage Tanks - Completed	Leaking Underground Storage Tanks - Completed	Voluntary Remediation: CGS 22a 133y Remediation Started	Leaking Underground Storage Tanks - Completed	Leaking Underground Storage Tanks – Investigation	Property Transfer – Form III Investigation started	Leaking Underground Storage Tanks – Completed	Leaking Underground Storage Tanks – Rem. Started	Leaking Underground Storage Tanks – Completed	Leaking Underground Storage Tanks – Completed	Leaking Underground Storage Tanks – Pending	Leaking Underground Storage Tanks – Completed	Leaking Underground Storage Tanks – Rem. Started	Leaking Underground Storage Tanks – Pending
						12/14/2016								
			6/26/2019											

"Hazardous Waste Facilities" as defined by Section 22a-134f of the Connecticut General Statutes

TOWN OF HAZITOZU	スープロスロ				Remedial			
Name	Address	Site Definition	Investigation Started	Remediation Started	Monitoring Started	Remediation Completed	ELUR	ELUR Type
40 Chapel Street	40 Chapel Street	Voluntary Remediation: CGS 22a 133x Remediation Started	6/27/2016	2/8/2018				
44 Imlay St	44 Imlay St	Leaking Underground Storage Tanks – Completed						
45-55 Bartholomew Avenue	45-55 Bartholomew Avenue	Voluntary Remediation: CGS 22a 133y Remediation Started		2/24/2015				
5860 Putnam St.	5860 Putnam St.	Leaking Underground Storage Tanks – Completed						
603-609 Franklin Avenue	603-609 Franklin Avenue	Property Transfer – Form III Remediation Started	6/6/2012	5/5/2015				
664 Prospect Ave. Reality	664 Prospect Ave.	Leaking Underground Storage Tanks – Completed						
7-11 Store #20691	894 Maple Avenue	Leaking Underground Storage Tanks – Rem. Started						
7-eleven #32957 (former Exxon Service Station #3-6943)	2120 Park Street	Leaking Underground Storage Tanks – Rem. Started						
7-eleven Store #20691	900 Maple Avenue	Voluntary Remediation: CGS 22a 133x Investigation started	2/19/2010					
7th Day Adventist Church	500 Woodland St	Leaking Underground Storage Tanks – Completed						
94 Hudson Street (parking Lot)	94 Hudson Street	Leaking Underground Storage Tanks – Completed						
Aaa Automobile Club	112 Prospect Ave.	Leaking Underground Storage Tanks – Completed						
Adams-ahearn	16-30 Arbor Street	Property Transfer – Form III Remediation Started	3/7/2006	3/4/2009				
Adco Citgo	618 Blue Hills Avenue	Leaking Underground Storage Tanks – Completed						
Adrien's Landing	100 Columbus Blvd	Leaking Underground Storage Tanks – Pending						

"Hazardous Waste Facilities" as defined by Section 22a-134f of the Connecticut General Statutes

Advanta Mortgage C/o Clemens 343 Fairfield Avenue	Name		
343 Fairfield Avenue	Address		
Leaking Underground Storage	Site Definition		
	Started		
	Started	Remediation	
	Started	Monitoring	Kemedial
	Completed	Remediation	
	ELUR		
	ELUR Type		

Alfred Mier	Albany Avenue Shell (former Shell Facility No. 136322)	Albany Avenue Mobil	Airport Truck Center	Aetna Ins. (atlas Tire)	Aetna Inmagineers Art Boothby	Aetna	Aetna	Aerospace Metals, Inc.	Aerospace Metals, Inc.	Aerospace Metals	Aero All Gas Company	Aenta Life Insurance	Advo-system, Inc.	Advanta Mortgage C/o Clemens Really
459 New Britain Ave	949 Albany Avenue	1510 Albany Avenue	50 Murphy Road	94 Hudson Street	44 Imlay Street	Imlay Street	1205 Farmington Ave.	500 Flatbush Avenue	500 Flatbush Avenue	500 Flatbush Avenue	3150 Main Street	151 Farmington Avenue	239 West Service Road	343 Fairfield Avenue
Leaking Underground Storage Tanks – Completed	Leaking Underground Storage Tanks – Completed	Leaking Underground Storage Tanks – Rem. Started	Property Transfer – Form III	Property Transfer – Form III	Leaking Underground Storage Tanks – Completed	Leaking Underground Storage Tanks - Completed	Leaking Underground Storage Tanks – Completed	Property Transfer – Form III Investigation started	Inventory of Hazardous Waste Disposal Sites	Leaking Underground Storage Tanks - Completed	Leaking Underground Storage Tanks – Investigation	Leaking Underground Storage Tanks – Rem. Started	Property Transfer – Form III Remediation Started	Leaking Underground Storage Tanks – Completed
								3/24/1998					3/17/2005	
													5/24/2005	
								YES						
								No Residential Use						

"Hazardous Waste Facilities" as defined by Section 22a-134f of the Connecticut General Statutes

OWN OT: HAKITOKU	AXITOXU				Remedial				
			Investigation	Remediation	Monitoring	Remediation			
Name	Address	Site Definition	Started	Started	Started	Completed	ELUR	ELUR Type	I
l Saints Church	205 Scarborough Street	Leaking Underground Storage							

Nume	Auuress	one Definition			Company	
All Saints Church	205 Scarborough Street	Leaking Underground Storage Tanks – Completed				
All Saints Russian Orthodox Church	All Saints Russian Orthodox Church	Leaking Underground Storage Tanks – Completed				
Allen Chapel Ame	2233 Main Street	Leaking Underground Storage Tanks – Completed				
Allied Plumbing Inc.	1477 Park Street	Leaking Underground Storage Tanks – Completed				
Alvin Carter	712 Broadview Terrace	Leaking Underground Storage Tanks – Completed				
Alvin Carter	712 Broadview Terrace	Leaking Underground Storage Tanks – Investigation				
American Masons And Building Supply Co.	3250 Main Street	Property Transfer – Form III Investigation started	1/23/2013			
American Masons And Building Supply Co. (former)	3250 Main Street	Property Transfer – Form III Investigation started	4/12/2018	2/13/2018		
American Masons And Building Supply Co. (former)	3250 Main Street	Property Transfer – Form III Remediation Started	4/12/2018	2/13/2018		
American School For Blind	120 Holcome	Leaking Underground Storage Tanks – Investigation				
Ameripride Linen & Apparel Services	490 Wethersfield Avenue	Leaking Underground Storage Tanks – Rem. Started				
Ameripride Services, Inc.	490, 484 And 482 Wethersfield Avenue	Property Transfer – Form III Investigation started	2/21/2018			
Amtrak New Haven-hartford- springfield Rail Line (milepost 37.3)	Market Street Extension (near 409 Windsor Street)	Leaking Underground Storage Tanks – Completed				
Andrew Poole	820 Prospect Ave	Leaking Underground Storage Tanks – Completed	a			
Apartment Building	22 Kenyon St.	Leaking Underground Storage Tanks – Completed				

"Hazardous Waste Facilities" as defined by Section 22a-134f of the Connecticut General Statutes

Ma	Re	
nitoring	medial	

TOWN OF: HAKIFOKU	スー・ロスロ		Remedial
<u>Name</u>	<u>Address</u>	Site Definition	Investigation         Remediation         Monitoring         Remediation           Started         Started         Started         Completed         ELUR Type
Apartment Building	63 Huntington Street	Leaking Underground Storage Tanks – Completed	
Apartment Complex	100 Sherbrook	Leaking Underground Storage Tanks – Investigation	
Apartment Complex	33 Imlay Street	Leaking Underground Storage Tanks – Completed	
Apple Car Star Collision Center	30 Airport Road	Property Transfer – Form III Investigation started	8/9/2005
Armsmear	80 Wethersfield Avenue	Leaking Underground Storage Tanks - Completed	
Army Reserve	Broad St.	Leaking Underground Storage Tanks – Completed	
Arrow-hart, Cooper Ind.	103 Hawthorn Street	Property Transfer – Form III	
Art Effects (former)	151 New Park Avenue	Property Transfer – Form III	
Art Theater	255 Franklin Ave.	Leaking Underground Storage Tanks – Investigation	
At&t Hartford Co #5161 (former Snet)	111 Trumbull Street	Leaking Underground Storage Tanks – Investigation	
At&t Hartford Garage	40 Brainard Road	Leaking Underground Storage Tanks – Rem. Started	
Atlas Oil	39 Elm Street	Property Transfer – Form III	
Atlas Oil Company	112 & 122 High Street	Property Transfer – Form III	
Atlas Oil Company - High Street Mobil	112 & 122 High Street	Property Transfer – Form III Investigation started	1/2/2020
Atlas Service Station	51 West Service Road	Leaking Underground Storage Tanks – Rem. Started	

"Hazardous Waste Facilities" as defined by Section 22a-134f of the Connecticut General Statutes

Name		WN OF: HA
Address		スーナロスロ
Site Definition		
Started	Investigation	
Started	Remediation	
Started	Monitoring	Remedial
Completed	Remediation	
ELUR		
ELUR Type		

Bernard Lapak	Bernard Lapak	Bernard Lapak	Berlin Oil (brainard Airport)	Benton Auto Body, Inc.	Barrieau Moving & Storage	Barrieau Moving & Storage	Barridon Corporation	Barridon Corp.(han-dee Spring Division)	Barhnat, Franics & Wild Inc.	Barbour Elementary School	Auto Zone / Payless Glass	Auto Parts Depot, Inc.	Auto Paint Distributors, Inc.	Allas Tower Avenue (former Mobil Station # 01-qqh And Atlas Oil)
7 Woodland	69 Gilette	30 Evergreen St.	155 West Service Rd.	85 Benton Street	301 Murphy Road	301 Murphy Road	1429 Park Street	1429 Park Street	339 - 341 New Park Avenue	150 Tower Avenue	555 Wethersfield Avenue	741 Windsor Street	320 Ann Street	275 Tower Avenue
Leaking Underground Storage Tanks – Completed	Leaking Underground Storage Tanks – Completed	Leaking Underground Storage Tanks – Completed	Leaking Underground Storage Tanks – Rem. Started	Property Transfer – Form III Investigation started	Property Transfer – Form III Remediation Started	Property Transfer – Form III Remediation Complete	Property Transfer – Form III Investigation started	Property Transfer – Form III Investigation started	Leaking Underground Storage Tanks – Completed	Leaking Underground Storage Tanks – Rem. Started	Leaking Underground Storage Tanks – Completed	Leaking Underground Storage Tanks – Completed	Property Transfer – Form III Investigation started	Leaking Underground Storage Tanks – Completed
				7/5/2019	1/26/2005	1/26/2005	7/17/2000	5/18/1999					10/26/2000	
					3/21/2011	3/21/2011								
					11/2/2005	11/2/2005								
						NO								

"Hazardous Waste Facilities" as defined by Section 22a-134f of the Connecticut General Statutes

TOWN OF: HAKITOKU	スー・ロスロ			Domadiation	Remedial		
<u>Name</u>	Address	Site Definition	<u>Started</u>	<u>Started</u>	Started	Started Completed	ELUR
Bernard Vinick	393-395 Wethersfield Ave.	Leaking Underground Storage Tanks – Completed					
Bethany Community Church	7 Charter Oak Place	Leaking Underground Storage Tanks – Completed	×				
Bill Roberts	171 Bloomfield Avenue	Leaking Underground Storage Tanks – Completed					
Bill's Auto	131 Buckingham Street	Leaking Underground Storage Tanks – Pending					
Bill's Automotive (former)	131 Buckingham Street	Property Transfer – Form III Investigation started	7/28/2017				
Brad Latham	195 Whitney St	Leaking Underground Storage Tanks – Completed					
Brainard Airport	233 Maxim Road (239 Maxim Road)	Leaking Underground Storage Tanks – Investigation					
Brainard Road Mobil (former Connecticut Freight & Emery & Purolator)	110 Brainard Road	Leaking Underground Storage Tanks – Rem. Started					
Brainard Road Shell (former Halprin's Texaco And Shell #100041)	131 Brainard Road	Leaking Underground Storage Tanks – Completed					
Braindard Oms-7a	269 Maxim Road	Leaking Underground Storage Tanks – Pending					
Brian Courtney	160 Oxford St	Leaking Underground Storage Tanks – Completed					
Bridgestone / Firestone, Inc.	1400 Main Street	Property Transfer – Form III Remediation Complete	12/9/2004	6/22/2005	12/22/2006	5/10/2011	NO
Bridgestone/firestone Inc.	1400 Main Street	Leaking Underground Storage Tanks – Completed					
Broad Park Development	Seymour Street	Leaking Underground Storage Tanks - Completed					

"Hazardous Waste Facilities" as defined by Section 22a-134f of the Connecticut General Statutes

### **TOWN OF: HARTFORD**

<u>Post</u> <u>Remedial</u>

Name  Name  Addra  Brookfield Auto Care  Budget One Hour Cleaners  294-308 Farmingtor	Address  8 Brookfield St. 294-308 Farmington Avenue	Site Definition  Leaking Underground Storage Tanks – Completed  Property Transfer - Form III Post Remedial Monitoring Started	<u>Started</u> 3/25/2004	Remediation Started	Remedial Monitoring Started 8/16/2005	Remediation Completed	ELUR NO	ELUR Type
Budget One Hour Cleaners	298 Farmington Avenue	Property Transfer – Form III						
Budget Rent-a-car	455 Farmington Avenue	Leaking Underground Storage Tanks – Rem. Started						
Burr School	400 Wethersfield Avenue	Leaking Underground Storage Tanks – Rem. Started						
C.p. Utilities	2880 Main Street	Leaking Underground Storage Tanks – Completed						
Cadet Cleaners (former)	48-54 Main Street	Property Transfer – Form III Investigation started	10/7/2014					
Caesars Auto Repair Center / K & N Auto	2940 Main Street	Property Transfer – Form III Investigation started	4/7/2003					
Calcoa Co. Div. Of Bell Pumps	3364h Main Street	Property Transfer – Form III Investigation started	2/6/2013					
Campbell Property	391 Fairfield Avenue	Leaking Underground Storage Tanks – Completed						
Capewell Manufacturing	Columbus Ave.	Leaking Underground Storage Tanks – Pending						
Capewell Manufacturing Site (former)	70 Popieluszko Court	Voluntary Remediation: CGS 22a 133y Remediation Started		9/1/2015				
Capital Region Mental Health Center (former Blue Hills Hospital)	51 Coventry Street - 52 Coventry Leaking Underground Storage Street Tanks - Completed	Leaking Underground Storage Tanks – Completed						
Capitol District Energy Center Cogeneration	490 Capitol Avenue	Property Transfer – Form III Investigation started	12/12/2001				YES	
Capitol Motors, Inc. Auto Body (former)	271 Windsor (tax Assessor Parcel 267-290-015)	Property Transfer – Form III Remediation Started	1/9/2015	2/17/2015				

"Hazardous Waste Facilities" as defined by Section 22a-134f of the Connecticut General Statutes

J			_
	Name		
	Address		
	Site Definition		
	Started	Investigation	
	Started	Remediation	
	Started	Monitoring	Remedial
	Completed	Remediation	
	ELUR		
	ELUR Type		

City Of Hartford	City Gas (former Frankal's Citgo)	Circle K Stores Inc.	Cigna Investment	Church Homes, Inc. (avery Heights)	Christopher Burns	Christirlano	Christ Church Rectory	Child & Family Services Inc.	Certified Associates(rental Company?)	Centrix Management	Cedar Hill Cemetary	Cecil's Auto Electric	Carter's Garage	Carangelo Residence
100 Vine Street Off Of Magnolia @ Milner Elementary School	10 White Street	159 Westland Street	30 Morris St.	705 New Britain Avenue	56 Scarborough Rd	65 Airport Road	118 Westerly Terr.	1680 Albany Avenue	958 Wethersfield Ave.	76 Webster Street	Cedar Hill Rd.	1496 Albany Avenue	104 Westland Street	234 North Beacon St.
Leaking Underground Storage Tanks – Completed	Leaking Underground Storage Tanks – Rem. Started	Leaking Underground Storage Tanks – Completed	Leaking Underground Storage Tanks – Investigation	Leaking Underground Storage Tanks – Completed	Leaking Underground Storage Tanks – Rem. Started	Leaking Underground Storage Tanks – Pending	Leaking Underground Storage Tanks – Completed	Leaking Underground Storage Tanks – Pending	Leaking Underground Storage Tanks – Investigation					

"Hazardous Waste Facilities" as defined by Section 22a-134f of the Connecticut General Statutes

ELUR Type	ELUR	Completed	Started	Started	Started	Site Definition	<u>Address</u>	<u>Name</u>
		Remediation	Monitoring	Remediation	Investigation			
			Remedial					YVIACI

3mmr	7.4444.000	Since De Clarente
City Of Hartford	1135 Albany Avenue To 1137 Albany Avenue	Leaking Underground Storage Tanks - Rem. Started
City Of Hartford	127 Huntington St	Leaking Underground Storage Tanks – Completed
City Of Hartford	155 Morgan Street	Leaking Underground Storage Tanks – Rem. Started
City Of Hartford	1750 Main St Sand School	Leaking Underground Storage Tanks – Rem. Started
City Of Hartford	188 Sigourney St.	Leaking Underground Storage Tanks – Pending
City Of Hartford	197 Main Street	Leaking Underground Storage Tanks – Completed
City Of Hartford	275 Pearl St.	Leaking Underground Storage Tanks – Completed
City Of Hartford	31 Wararme Ave	Leaking Underground Storage Tanks – Completed
City Of Hartford	38 - 70 Park Street	Leaking Underground Storage Tanks - Completed
City Of Hartford	555 Windsor St.	Leaking Underground Storage Tanks – Completed
City Of Hartford	915 Main St.	Leaking Underground Storage Tanks – Completed
City Of Hartford	Canton & Windsor	Leaking Underground Storage Tanks – Investigation
City Of Hartford	Dutch Point	Leaking Underground Storage Tanks - Completed
City Of Hartford	Nelton Ct.	Leaking Underground Storage Tanks – Pending
City Of Hartford	Overlook Terr.	Leaking Underground Storage Tanks – Investigation

"Hazardous Waste Facilities" as defined by Section 22a-134f of the Connecticut General Statutes

### **TOWN OF: HARTFORD**

<u>Post</u> <u>Remedial</u>

Name  Addre  City Of Hartford  City Of Hartford  City Of Hartford - Acquisitions - 35 Cleveland Avenual Gus Espinoza	Address  South Coventry St.  Weathersfield Avenue  35 Cleveland Avenue	Site Definition  Leaking Underground Storage Tanks – Completed  Leaking Underground Storage Tanks – Completed  Leaking Underground Storage Tanks – Completed	<u>Started</u>	<u>Remediation</u> <u>Started</u>	The state of the s	Remedial  Monitoring Remediation  Started Completed	ELUR
City Of Hartford - Acquisitions - Gus Espinoza	35 Cleveland Avenue	Leaking Underground Storage Tanks – Completed					
City Of Hartford Pope Park Pumping Station	Park Terrace, Pope Park Pumping Station	Leaking Underground Storage Tanks – Completed					
Cily Of Hartford, Sal Papatto	754 Maple Avenue	Leaking Underground Storage Tanks – Completed					
City Of Httd Parks Dept	Wethersfield Ave.	Leaking Underground Storage Tanks – Completed					
City Sheller	98 Huyshope Ave.	Leaking Underground Storage Tanks – Completed					
City Tire Company	100 Airport Road	Leaking Underground Storage Tanks – Investigation					
Cl&p	Reserve Road & Maxim Road	Property Transfer – Form III Investigation started	5/23/2001				
Cl&p	Reserve Road (gate 20)	Property Transfer – Form III Remediation Started	5/1/2009	3/8/2013			
Cloud Res.	24 Woodside Circle	Leaking Underground Storage Tanks – Completed					
Cogswell Ave. Parking Lot	Cogswell Avenue	Leaking Underground Storage Tanks – Completed					
Coleman's Quality Cleaners (fka Hayes Cleaners)	3125-3159 Main Street	Property Transfer – Form III Investigation started	3/1/1999				
Colt Firearms	150 Huyshope Avenue	Property Transfer – Form III					
Colt Firearms (colt)	150 Huyshope Avenue	Property Transfer – Form III					

"Hazardous Waste Facilities" as defined by Section 22a-134f of the Connecticut General Statutes

**TOWN OF: HARTFORD** 

<u>Post</u>

<u>Remedial</u>

<u>Investigation Remediation Monitoring Remediation</u>

<u>Started Started Started Completed ELUR Type</u>

Con / Cp	Connect Compar Utilities)	Con	Con	Con	Con	Con Trar	Com	Com	Сол	Colt	Colt	Colt	Colt	Colt Fire
Connecticut Power Systems, Llc / Cpc, Inc.	Connecticut Light And Power Company (former Northeast Utilities)	Connecticut Company	Connecticut Company	Connecticut Cleaners	Connecticut Cleaners	Conn. Department Of Transportation	Community Renewel Team	Community Health Services	Comet Diner (former)	Coltsville Heritage Park	Coltsville Heritage Park	Coltsville Heritage Park	Colt Park	Colt Industrial Park (former Colt Firearms And Water & Way)
260 Murphy Road	400 Sheldon Street	Allyn, High, Church Street	2909 Main Street	274 Farmington Avenue	274 Farmington Avenue	53 Vernon Street	32-36 Wethersfield Ave.	520 Albany Ave.	267 Farmington Avenue And 291 Laurel Street	36 Huyshope Avenue	25 Van Dyke Avenue	25 Van Dyke Avenue	Warwamee Ave.	140 Huyshope Avenue - 150 Huyshope Avenue
Property Transfer – Form III Remediation Started	Leaking Underground Storage Tanks – Completed	Property Transfer – Form III	Property Transfer – Form III	Property Transfer – Form III Remediation Complete	Property Transfer – Form III Investigation started	Property Transfer – Form IV Remediation Started	Leaking Underground Storage Tanks – Completed	Leaking Underground Storage Tanks – Rem. Started	Voluntary Remediation: CGS 22a 133x	Property Transfer – Form III Remediation Started	Property Transfer – Form III Investigation started	Property Transfer – Form III Investigation started	Leaking Underground Storage Tanks – Completed	Leaking Underground Storage Tanks - Completed
9/29/2003				2/20/2007	2/2/2005	3/29/1999				3/26/2003	8/11/2005	8/11/2005		
2/12/2009						3/29/1999				6/25/2013				
				8/17/2007							95			
				NO										

"Hazardous Waste Facilities" as defined by Section 22a-134f of the Connecticut General Statutes

Connecticut Resource Recovery 300 Maxim Road	<u>Name</u>		TOWN OF: HARTFORD
00 Maxim Road	Address		TFORD
Leaking Underground Storage	Site Definition		
	Started	Investigation	
	Started	Remediation	
	Started	Monitoring	Remedial
	Completed	13800	
	ELUR		
	ELUR Type		

Ct Light & Power	Ct Drug & Alcohol Commission	Ct Dot New Britian To Hartford Busway Project - Streetscape Improvements	Crown Cleaners Inc.	Crec	Coss 00583 (former Getty Station)	Cosgrove Residence	Corp. For Independent Living	Cooper Industries	Contractors Consultants & Managers	Constitution Plaza	Connecticut Transit	Connecticut Transit	Connecticut River Plaza	Connecticut Resource Recovery
400 Sheldon Street	2 Holcomb St.	1659 Park Street	297 Franklin Avenue	236 Wethersfield Ave.	366 Homestead Avenue	229 Oxford Street	26 - 28 Babcock Street	103 Hawthorn Street	7 May Street	1, 10, 100, 248, 250 And 260 Constitution Plaza	53 Vernon Street	100 Leibert Road (intersection With Jennings Road)	450 Columbus Boulevard	300 Maxim Road
Leaking Underground Storage Tanks – Completed	Leaking Underground Storage Tanks – Completed	Leaking Underground Storage Tanks – Completed	Property Transfer – Form III Investigation started	Leaking Underground Storage Tanks – Completed	Property Transfer – Form III	Leaking Underground Storage Tanks – Completed	Property Transfer – Form III Remediation Complete	Leaking Underground Storage Tanks – Rem. Started	Leaking Underground Storage Tanks – Rem. Started	Leaking Underground Storage Tanks – Completed	Leaking Underground Storage Tanks – Rem. Started			
			11/28/2005							8/20/2015				
										5/11/2018				
										NO				

"Hazardous Waste Facilities" as defined by Section 22a-134f of the Connecticut General Statutes

Ct Mutual Life Co.	Name			TOWN OF HARTEORI
140 Garden St.	Address			BTEOBD
Leaking Underground Storage Tanks – Pending	Site Definition			
	Started	Investigation		
	Started	Remediation		
	Started	Monitoring	Remedial	Post
	Completed	Remediation		
	ELUR			
	ELUR Type			

						6	
Ct Mutual Life Co.	140 Garden St.	Leaking Underground Storage Tanks – Pending					
Ct River Adjacent To Adriens Landing	Columbus Blvd	Leaking Underground Storage Tanks – Pending					
C-town Supermarket	C-town Supermarket 165 Wethersfield Avenue	Leaking Underground Storage Tanks – Completed					
Cty Htd Womens Shelter	322 Washington	Leaking Underground Storage Tanks – Completed					
Cushman Industries, Inc.	780-818 Windsor Street	Property Transfer – Form III					
Cushman Industries,inc. (former)	780a-806 Windsor Street	Property Transfer – Form III Investigation started	11/3/2016				
D & D Market	276 Franklin Avenue	Leaking Underground Storage Tanks – Rem. Started					
Daigle's Auto Body Shop	147 Charter Oak Avenue	Property Transfer - Form III Post Remedial Monitoring Started	7/30/2013	8/14/2013	7/25/2017	NO	
Dairy Mart Service Station #1544	923 Maple Avenue	Voluntary Remediation: CGS 22a,- 133x Remediation Started	1/16/2001	4/2/2012			
Dale Blake	194 Kenyon Street	Leaking Underground Storage Tanks – Completed					
Daniel Zak	1063-1065 Capitol Avenue	Leaking Underground Storage Tanks – Completed					
Dave Bilken	153 North Bergen	Leaking Underground Storage Tanks – Rem. Started					
David Hamadi	116 New Britain Avenue	Leaking Underground Storage Tanks – Completed					
David Lattorzori	18 Niles Street	Leaking Underground Storage Tanks – Completed					
Db Oil Coproration (former Mobil Station #06-037)	519 Farmington Avenue	Leaking Underground Storage Tanks – Rem. Started					

"Hazardous Waste Facilities" as defined by Section 22a-134f of the Connecticut General Statutes

TOWN OT: HAKITOKU	スープロスロ				Remedial			
Namo	Addross	Site Definition	Investigation Started	Remediation Monitoring Started Started		Remediation Completed	ELUR	ELUR Type
Db Oil Corp D/b/a Hartford Mart	519 Farmington Avenue	Property Transfer – Form III Remediation Started	10/26/2011	4/4/2014				
Dennis Padwater	40 North Beacon Street	Leaking Underground Storage Tanks – Completed						
Dent 'n Scratch	91 Airport Road	Property Transfer – Form III Investigation started	3/3/2015					
Dept. Public Works	40 Jennings Road	Leaking Underground Storage Tanks – Completed						
Devcon	609 Farmington Avenue	Leaking Underground Storage Tanks – Completed						
Devino-babe Mercury Fuel Service, Inc.	888 New Britain Avenue	Leaking Underground Storage Tanks – Rem. Started						
Dick Whitehouse	186 Collins St.	Leaking Underground Storage Tanks – Completed						
Dillon Place Associates	54 -84 Hendrixson Ave.	Leaking Underground Storage Tanks – Completed						
Dono Parcel G	150 Windsor Street	Property Transfer – Form III Investigation started	8/4/2015	į.				
Dono Parcel G	150 Windsor Street	Property Transfer – Form III Investigation started	8/4/2015					
Douglas Andrews	59 Canterbury Street	Leaking Underground Storage Tanks – Completed						
Dph Laboratory (former)	120 Capitol Avenue Formerly 79 Elm Street Rear	Property Transfer – Form III Remediation Started		7/27/2020				
Dps Dsp Troop H (police Barracks)	100 Washington Street	Leaking Underground Storage Tanks – Completed						
Dr Betances School	42 Charter Oak Avenue	Leaking Underground Storage Tanks – Rem. Started						
Dresser Ind / Whitney Chain	121 Wawarme Avenue	Property Transfer – Form III Remediation Started	2/20/2014	1/10/2017				

"Hazardous Waste Facilities" as defined by Section 22a-134f of the Connecticut General Statutes

TOWN OF: MAXIFOXU	スートロスロ				Remedial			
Vama	Address	Sito Dofinition	Investigation Started	Remediation Started	Monitoring Started	Remediation Completed	ELUR	ELUR Type
Driscoll Motors - Godell's Body Shop	128-180 Allyn Street, 84-110 High Street, 317-331	Property Transfer – Form III Investigation started	1/2/2020					
Driscoll Motors (see Conn Co.)	132 Allyn Street	Property Transfer – Form III						
Dunkin Donuts	Dunkin Donuts 75 Airport Rd	Leaking Underground Storage Tanks – Completed						
Dwight Bellizi Asia Studies Academy	215 South Street	Leaking Underground Storage Tanks - Completed						
East Coast Petroleum	143 Murphy Road	Leaking Underground Storage Tanks – Rem. Started						
Ed Page	55 Grant St.	Leaking Underground Storage Tanks – Completed						
Edart Leasing Company, Llc	185 West Service Road & 70 Fishfry Street	Property Transfer – Form III Remediation Started	4/6/2009	4/22/2016				
Edart Leasing Company. Llc	185 West Service Road 70 Fishfry Street	Property Transfer – Form III Investigation started	3/5/2009					
Edward Bialaskorski	37 Montrose St.	Leaking Underground Storage Tanks – Completed						
Egan Residence	193 Kenyon Street	Leaking Underground Storage Tanks – Completed						
Electrical Wholesalers, Inc. (former)	51 Homestead Avenue	Property Transfer – Form III Remediation Started	2/27/2015	3/23/2018				
Elizabeth Park	Prospect Ave.	Leaking Underground Storage Tanks – Completed						
Emmanuel Congregational Church	360 Farmington Ave.	Leaking Underground Storage Tanks – Completed						
Engine Company #5	319 Sigourney Street	Leaking Underground Storage Tanks – Pending						
Equipment Service, Inc.	40 Airport Road	Property Transfer – Form III						

"Hazardous Waste Facilities" as defined by Section 22a-134f of the Connecticut General Statutes

Properly Transfer - Form III   Signifon   Remediation   Monitoring   Remediation   Monitoring   Remediation   ELUR   Remediation   ELUR   Remediation   ELUR   Remediation   ELUR   ELUR   Remediation   ELUR   EL	Finn's Supermarket	Ferrablo Residence	Fas Mart 332 (former Dairy Mart #1544 And Qp Mart Store #h332d)	Fas Mart (former Dbm #542)	Exxon Service Station Ras #3-6943	Exxon Service Station	Exxon Ras #3-6943	Exxon #38218	Evergreen Food Mart Llc	Evelyn Schwolski	Evarts Machine Company, Inc.	Evan Sokale	Euarts Mfg Company	Equity Bank, (owners)	Equipment Service, Inc.	<u>Name</u>	TOWN OF: HARTFORD
Investigation Remediation Monitoring Remediation Started Started Started Completed ELUR  530/1957  530/1957  627/2002  627/2002  676/2015 NO	200-198 Farmington Ave.	32 Sission Avenue	923 Maple Avenue	867 Wethersfield Avenue	2120 Park Street	4 Weston Street	2120 Park Street	265 Washington Street	634 Wethersfield Avenue	59 Bloomfield Ave	21 Francis Avenue	140 Elizabeth Street	21 Francis St.	91-93 Airport Road	40 Airport Road	Address	RTFORD
Investigation Remediation Monitoring Remediation Started Started Started Completed ELUR  5/30/1997  6/27/2002  8/12/12/2006  Post Remediation Monitoring Remediation Started Completed ELUR  6/16/2015 NO	Leaking Underground Storage Tanks – Completed	Leaking Underground Storage Tanks – Completed	Leaking Underground Storage Tanks - Completed	Leaking Underground Storage Tanks – Rem. Started	Voluntary Remediation: CGS 22 133x Investigation started	Leaking Underground Storage Tanks – Rem. Started	Voluntary Remediation: CGS 22 133x Remediation Complete	Leaking Underground Storage Tanks – Completed	Leaking Underground Storage Tanks – Rem. Started	Leaking Underground Storage Tanks – Completed	Property Transfer – Form III Investigation started	Leaking Underground Storage Tanks – Completed	Leaking Underground Storage Tanks – Completed	Leaking Underground Storage Tanks – Completed	Property Transfer – Form III Investigation started	Site Definition	
110							7/21/2006				6/27/2002				5/30/1997	Started Started Completed	Remediation

"Hazardous Waste Facilities" as defined by Section 22a-134f of the Connecticut General Statutes

Former Jiffy Lube Store #267	Former Holiday Drive-in Cleaners And Country	Former Gasoline Station	Former Gas Station	Former Comet Diner	Former Circle K #2784621 (former Citgo)	Fomer Homestead Station	Fleet National Bank	Firehouse #14	Firehouse #10	Fire House #2	Fire Dept. Maintenance	Fire Dept.	Fire Dept.	Fire Department Engine #5	Name	TOWN OF: HARTFORD
10 Weston Ave	888 Wethersfield Avenue	Intersection Of Zion Street And Park Street	202 Albany Avenue	267 Farmington Avenue	1127 Capitol Avenue	185 Homestead Avenue	777 Main Street	25 Blue Hills Avenue	510 Franklin Avenue	1515 Main Street	36 John St.	636 Blue Hills Ave.	181 Clark St.	127 Sigourney Street	Address	ARTFORD
Leaking Underground Storage Tanks – Completed	Property Transfer – Form III	Leaking Underground Storage Tanks – Pending	Leaking Underground Storage Tanks – Rem. Started	Leaking Underground Storage Tanks – Pending	Leaking Underground Storage Tanks - Rem. Started	Leaking Underground Storage Tanks – Completed	Property Transfer – Form III Remediation Complete	Leaking Underground Storage Tanks – Pending	Leaking Underground Storage Tanks – Completed	Leaking Underground Storage Tanks – Rem. Started	Site Definition					
							8/30/2004								E .	Investigation Remediation
																<u>Post</u> <u>Remedial</u> iation Monitoring Remediation
							10/9/2013 NO								Completed ELUR	Remediation
															ELUR Type	

"Hazardous Waste Facilities" as defined by Section 22a-134f of the Connecticut General Statutes

<b>TOWN OF: HARTFORD</b>	RTFORD				<u>Post</u> Remedial			
<u>Name</u>	Address	Site Definition	<u>Investigation Remediation Monitoring Remediation</u> <u>Started Started Completed ELUR Type</u>	nediation Started	Monitoring Started	Remediation Completed	<u>ELUR</u>	ELUR Type
Former M. Swift & Sons	10 Love Lane	Leaking Underground Storage Tanks – Rem. Started						
Former Mass Mutual	140 Garden Street	Leaking Underground Storage Tanks – Rem. Started						
Former Merit Station	430-460 Albany Ave	Leaking Underground Storage Tanks – Rem. Started						
Former Mobil Station 01-et1	1157 Albany Avenue To 1161 Albany Avenue	Leaking Underground Storage Tanks – Rem. Started						
Former Shell Service Station	3108 Main Street To 3122 Main Street	Leaking Underground Storage Tanks – Pending						
Francine Gionfriodo	272-276 South Marshal St.	Leaking Underground Storage Tanks – Completed						
Fred Galli	183 Oxford Street	Leaking Underground Storage Tanks – Completed						
Frederica Congdon	967-969 West Boulevard	Leaking Underground Storage Tanks – Completed						
Furniture Company	Asylum St.	Leaking Underground Storage Tanks – Completed						
G.b. Family Auto Body (former)	12-14 New Park Avenue	Property Transfer – Form III Investigation started	10/23/2018					
Gadell's Repair (see Conn Co.)	98 High Street	Property Transfer – Form III						
Gary Strickland	232 Oxford St	Leaking Underground Storage Tanks – Completed						
Ge Captial	85 Woodland Street	Leaking Underground Storage Tanks – Pending						
General Elevator Co., Inc.	181-191 Walnut Street	Inventory of Hazardous Waste Disposal Sites						
General Elevator Co., Inc.	181-191 Walnut Street	Property Transfer – Form III						

#### Thursday, January 14, 2021

# List of Contaminated or Potentially Contaminated Sites

"Hazardous Waste Facilities" as defined by Section 22a-134f of the Connecticut General Statutes

#### MOT

Name	Addross	Site Definition	Investigation Started	Remediation	Monitoring Started	Remediation	FIIIR	ELUR Type
Name	Address	Site Definition	Started	Started	5	Countated	FILIR	ELUI

Hanmer Properties	H F W Realty - Contact Milton Rulnick	H & S Corporation (former Amoco)	Gulf	Grimm & Ronco	Greg Kunz	Greater Hartford Comm. College	Grace Worship Center Church	Goran Investors	Goran Investors	Goodwin Park	Gold Bond Mattress	Getty Petroleum	George's Tire Service	Gengras Motor Cars
99 Hanmer Street	195-201 Locus Street	1330 Albany Avenue	182 Washington Street	747 Maple Avenue	100 Campfield Ave	Asylum Ave.	750 Wethersfield Avenue	21 Evergreen Street	154 Collins St.	Ridge Road	North Main St. (801 Windsor Street)	366 Homestead Avenue	41 Hillside Avenue	1 Weston Park Road
Property Transfer – Form III Investigation started	Leaking Underground Storage Tanks – Completed	Leaking Underground Storage Tanks – Rem. Started	Leaking Underground Storage Tanks – Completed	Voluntary Remediation: CGS 22a,- 133y Remediation Started	Leaking Underground Storage Tanks – Completed	Leaking Underground Storage Tanks – Completed	Leaking Underground Storage Tanks – Investigation	Leaking Underground Storage Tanks – Completed	Property Transfer – Form III	Leaking Underground Storage Tanks – Completed	Leaking Underground Storage Tanks – Investigation			
6/9/2003												8		
							11/8/2010							

Page 99 of 255

#### Thursday, January 14, 2021

# List of Contaminated or Potentially Contaminated Sites

"Hazardous Waste Facilities" as defined by Section 22a-134f of the Connecticut General Statutes

7	I	Ha I	Ha	На	На	Ha	Ha	На	Ha	Ha	Ha Plu	На Се	Ha	Ha	Ha	
TOWN OF: HARTFORD	Name	Harsco Corporation	Hartford Armory And Oms #8a	Hartford Board Of Ed	Hartford Builder's Finish Co.	Hartford Bus Co.	Hartford Car Wash	Hartford Car Wash	Hartford Central Office #6 (5123)	Hartford Central Office (5114)	Hartford Citgo (former Petrol Plus)	Hartford Community Correction Center	Hartford Cooperage	Hartford Courant	Hartford Courant Co	Hartford Courant Distribution
RTFORD	Address	540 Flatbush Avenue	360 Broad Street	High St.	34 Potter Street	Weston Street	2434-2470 Main Street	2434-2470 Main Street	105 Ledyard Street	520 New Britain Avenue	351 Woodland Street	177 Weston Street	505 Hudson Street	313 Jefferson St.	121 Wawarme Avenue	132 Elliot Street East (134 Elliot
,	Site Definition	Property Transfer – Form III Investigation started	Leaking Underground Storage Tanks – Rem. Started	Leaking Underground Storage Tanks – Completed	Property Transfer – Form III	Leaking Underground Storage Tanks – Pending	Property Transfer – Form III Investigation started	Property Transfer – Form III Remediation Started	Leaking Underground Storage Tanks – Completed	Inventory of Hazardous Waste Disposal Sites	Leaking Underground Storage Tanks – Completed	Leaking Underground Storage Tanks – Completed	Leaking Underground Storage			
Investigation		12/7/2018					2/18/2004	6/9/2006								
Remediation	Started							3/1/2010								
<u>Post</u> <u>Remedial</u> Monitoring	Started															
<u>Post</u> <u>Remedial</u> Monitoring Remediation	Completed		8													
	ELUR															
	ELUR Type															

"Hazardous Waste Facilities" as defined by Section 22a-134f of the Connecticut General Statutes

TOWN OF: HARTFORD  Name  Addre  Hartford Dispensary  Hartford Faience Company  175 Bartholomew Average of the company  175 Bartholomew Average of the company	RTFORD  Address  345 Main Street  175 Bartholomew Avenue	Site Definition  Leaking Underground Storage  Tanks – Completed  Property Transfer – Form III Investigation started	Investigation Started  4/24/2019	Remediation Started	Remedial Monitoring Started	Remediation Completed	ELUR
Hartford Faience Company (former)	175 Bartholomew Avenue	Property Transfer – Form III Investigation started	4/24/2019				
Hartford Fire Insurance Company 690 Asylum Avenue	690 Asylum Avenue	Leaking Underground Storage Tanks – Completed					
Hartford Foodland (former Shell Facility Cc No. 136321)	831 Maple Avenue	Leaking Underground Storage Tanks – Completed					
Hartford Gas Island (buckingham Garage)	309 Buckingham Street	Leaking Underground Storage Tanks – Rem. Started					
Hartford Hospital	80 Seymour Street	Leaking Underground Storage Tanks – Completed					
Hartford Hospital	80 Seymour Street	Leaking Underground Storage Tanks – Completed					
Hartford Hospital Hundson Street Parking Garage Project	75 Park Street	Leaking Underground Storage Tanks – Completed					
Hartford Housing Authority	73 Vine Street	Leaking Underground Storage Tanks – Completed					
Hartford Housing Authority	Granby St.	Leaking Underground Storage Tanks – Completed					
Hartford Landfill	180 East Service Road	Inventory of Hazardous Waste Disposal Sites					
Hartford Lumber Co.	20 Chestnut St.	Leaking Underground Storage Tanks – Completed					
Hartford Maintenance Facility	49 Jennings Road	Leaking Underground Storage Tanks – Investigation					
Hartford Oil Corp. (former Shell 136325)	1620 Park Street	Leaking Underground Storage Tanks – Completed					
Hartford Police Station	50 Jennings Road	Leaking Underground Storage Tanks – Investigation					

#### Thursday, January 14, 2021

# List of Contaminated or Potentially Contaminated Sites

"Hazardous Waste Facilities" as defined by Section 22a-134f of the Connecticut General Statutes

Name  Mame  Manne  Manne  Manne  Addree  Addree  Hartford Public High School  Hartford Square North  Hartford Square North  Hartford Square North  Hartford Square North  Hartford-empire Company  Harvey Bennett  Harvey Robbin Company  Harvey Robbin Comp	Address  4 ddress  55 Forest Street  10 Columbus Blvd  10 Columbus Blvd  10 Columbus Blvd  393 Homestead Avenue  3940 Main Street  1919 Broad Street  1919 Broad Street  380 Capitol Avenue (376 Capitol Avenue - 400 Capitol Avenue)	Site Definition  Leaking Underground Storage Tanks – Rem. Started  Property Transfer – Form III Investigation started  Voluntary Remediation: CGS 22a 133x Investigation started  Voluntary Remediation: Storage Tanks – Completed  Leaking Underground Storage Tanks – Completed  Property Transfer – Form III  Property Transfer – Form III  Property Transfer – Form IIII  Property Transfer – Form IIII	Investigation Started  9/26/2019  - 4/11/2000  - 7/11/2017	Remediation Started 7/19/2017	<u>Remedial</u> <u>Monitoring</u> <u>Started</u>	Remediation Completed	ELUR NO
rd Public High School rd Square North	55 Forest Street 10 Columbus Blvd	Leaking Underground Storage Tanks – Rem. Started Property Transfer – Form III Investigation started	9/26/2019				
Hartford Square North	10 Columbus Blvd	Voluntary Remediation: CGS 22a. 133x Investigation started					
lartford-empire Company	393 Homestead Avenue	Voluntary Remediation: CGS 22a. 133x Remediation Started		7/19/2017			
Harvey Bennett	101 Airport Road	Leaking Underground Storage Tanks - Completed					
Harvey Robbin Company	2940 Main Street	Leaking Underground Storage Tanks - Completed					
Hawk's Getty Station (getty #06826)	1919 Broad Street	Leaking Underground Storage Tanks - Completed					
Henry Zahchs	380 Capitol Avenue (376 Capitol Avenue - 400 Capitol Avenue)	Leaking Underground Storage Tanks - Completed					
Hertz Corp. (see Conn Co.)		Property Transfer – Form III					
Hertz-penske Truck Leasing Facility	61 Fishfry Street	Property Transfer – Form III Remediation Complete	12/12/2006	8/14/2013			3/11/2019
Heublein, Inc.	330 New Park Avenue	Voluntary Remediation: CGS 22a,-133x Investigation started	2/28/1997				
Heublein, Inc. Udv North America 330 New Park Avenue	a 330 New Park Avenue	Property Transfer – Form IV Remediation Started	8/27/1999	8/27/1999			
Heublein, Inc./udv North America (former)	330 New Park Avenue	Property Transfer – Form III Investigation started	2/21/2018				
Heublein, Inc./udv North America (former)	330 New Park Avenue	Property Transfer – Form III Investigation started	2/21/2018				
Hi-g Company, Inc.	101 Locust Street	Property Transfer – Form III					

#### Thursday, January 14, 2021

# List of Contaminated or Potentially Contaminated Sites

"Hazardous Waste Facilities" as defined by Section 22a-134f of the Connecticut General Statutes

Post

<b>TOWN OF: HARTFORD</b>	RTFORD				Post Romedial			
<u>Name</u>	Address	Site Definition	Investigation Started	Remediation Started	Monitoring Started	<u>Remediation</u> <u>Monitoring</u> <u>Remediation</u> <u>Started</u> <u>Started</u> <u>Completed</u>	ELUR	ELUR ELUR Type
Hillside Automotive Center Inc.	54 Hillside Avenue	Leaking Underground Storage Tanks – Rem. Started						
Hilltop Cleaners	241-243 Sigourney Street	Property Transfer – Form III						
Horizon Management	41 Huntington Street, Horizon Management	Leaking Underground Storage Tanks – Completed						
Horizon Management	99 Hunnington	Leaking Underground Storage Tanks – Completed						
Howard Mc Lendon	263 Capen	Leaking Underground Storage Tanks – Completed						
Howard, Cohn, Sprague & Fitzge	Cedar St.	Leaking Underground Storage Tanks – Completed						
Hp Koppelmann Inc.	140 Van Block Avenue	Leaking Underground Storage Tanks – Completed						
Hpm Corporation	270 Locust Street	Property Transfer – Form III Investigation started	4/1/1999					
Hud/ Ed Simmoms Utility Devel. Corp.	63-65 Willis St.	Leaking Underground Storage Tanks – Completed						
Hudson Holdings Llc	151 Earl Street	Leaking Underground Storage Tanks – Rem. Started						
Hudson Laundry	439 Homestead Avenue - 455 Homestead Avenue	Leaking Underground Storage Tanks - Completed						
Hudson Park Development Corp.	505 Hudson Street	Property Transfer – Form III						
l.d.v. America (former Hueblien)	330 New Park Avenue	Leaking Underground Storage Tanks – Completed						
I.s.d.s. Real Estate	10 Niles Street	Leaking Underground Storage Tanks – Completed						
Independent Living Corp.	22-24 Babcock St Independent Living Corp.	Leaking Underground Storage Tanks - Completed						

"Hazardous Waste Facilities" as defined by Section 22a-134f of the Connecticut General Statutes

RTFORD

Post

_	-
IAA	
1	
C	
7	7
1	
Z	J
Ξ	7
Ċ	j
7	J
	J

TOWN OF: HARTFORD	RTFORD			Damadiation	Remedial	Jan Jan A		
<u>Name</u>	Address	Site Definition	Started	<u>Started</u>	Started Completed	Completed	ELUR	ELUR Type
Iri Holdings, Inc.	85 Woodland Street	Property Transfer – Form IV Remediation Complete	12/9/2004			6/22/2007	NO	
lss Prudential (see Conn Co.)	100 High Street	Property Transfer – Form III						
J & D Performance (waller Property)	3311 Main Street	Leaking Underground Storage Tanks – Rem. Started						
Jag's Service Station	946 Maple Ave.	Leaking Underground Storage Tanks – Rem. Started						
Jeff Daniels	244-246 Oxford Street	Leaking Underground Storage Tanks - Completed						
Jeff Reiner	148-152 Collins Street	Leaking Underground Storage Tanks Completed						
Jefferson Park, Inc.	80 Jefferson Street	Inventory of Hazardous Waste Disposal Sites						
Jefferson Park, Inc.	80 Jefferson Street (aka Hudson Property Transfer – Form III Street)	Property Transfer – Form III						
John Mcclure	806 Prospect Avenue	Leaking Underground Storage Tanks - Completed						
John's Auto Inc.	284 Locust Street	Property Transfer – Form III Remediation Complete	6/21/2005			9/2/2014	NO	
John's Auto Inc.	284-300 Locust Street	Property Transfer – Form III Investigation started	3/20/2003					
Johnson Controls	603-609 Franklin Avenue	Property Transfer – Form III Investigation started	8/9/2005					
Johnson Controls	605 Franklin Ave.	Leaking Underground Storage Tanks Completed						
Johnson Controls Inc.	603-609 Franklin Avenue	Property Transfer – Form III Investigation started	3/5/2008					
Johny's Automotive	201 Buckingham Street	Leaking Underground Storage Tanks – Rem. Started						

Thursday January 14 2021

"Hazardous Waste Facilities" as defined by Section 22a-134f of the Connecticut General Statutes

Joseph Merritt & Company, Inc. 650 Franklin Avenue	<u>Name</u>	TOWN OF HARITORD
650 Franklin Avenue	Address	スープロスロ
Leaking Underground Storage Tanks – Rem. Started	Site Definition	
	<u>Investigation Remediation Monitoring Remediation</u> <u>Started Started Started Completed ELUR Type</u>	Post
	vpe	

Larry Automotive	Larkin Residence	Lanz Parking	Laidlaw Bus Terminal	L. Leblanc	Kwk Hanmer Llc	Kibby Car Care	Kessler Installation Corporation	Kent Cleaners (former)	Kent Cleaners (former)	Kenney Golf Course	Keney Land Pump Station	Kansas Etheridge	Justus Johnson & Sons	
1511 Albany Avenue	71 Scarboro Road	Hudson Street	2909 Main Street	48-50 Buckley Ave	99 Hanmer Street	760 Windsor Street	244 Prospect Avenue	887-891 Park Street	887-891 Park Street	280 Tower Avenue	Polter Street	71 Milford St	22 Orange Street	
Leaking Underground Storage Tanks – Rem. Started	Leaking Underground Storage Tanks - Completed	Leaking Underground Storage Tanks - Completed	Leaking Underground Storage Tanks – Completed	Leaking Underground Storage Tanks – Completed	Leaking Underground Storage Tanks – Investigation	Property Transfer – Form IV Remediation Started	Leaking Underground Storage Tanks – Rem. Started	Property Transfer – Form III Remediation Started	Property Transfer – Form III Investigation started	Leaking Underground Storage Tanks – Completed	Leaking Underground Storage Tanks – Rem. Started	Leaking Underground Storage Tanks – Completed	Property Transfer – Form III Investigation started	Tanks - Rem. Started
						9/7/1999		1/26/2016	1/26/2016				1/26/2005	
					¥	9/7/1999		11/30/2015	11/30/2015					

"Hazardous Waste Facilities" as defined by Section 22a-134f of the Connecticut General Statutes

Name  Name  Addre  Lavery Appliance  Leopold Green - Greens Autobody  Lewtan Industries  Loomis Armored Inc.  Loomis Armored Inc.  Loomis Armored Inc.  To Maxim Road  Lucio Panno  M & Z Cleaners / Goodwin Square  M. Swift & Sons Inc.  Addre  Sigourney St.  40 Webster Street  2760 Thru 2786 Ma  2760 Thru 2786 Ma  103-105 Allyn Street  175 Maxim Road  170-172 Roosevelt  170-172 Roosevelt  Allove Lane  M. Swift & Sons Inc.  10 Love Lane	Address  Address Sigourney St.  40 Webster Street 2760 Thru 2786 Main Street 103-105 Allyn Street 175 Maxim Road 170-172 Roosevelt St 225 Asylum Avenue	Leaking Underground Storage Tanks – Completed Property Transfer – Form III Investigation started Leaking Underground Storage Tanks – Completed Leaking Underground Storage Tanks – Rem. Started Leaking Underground Storage Tanks – Rem. Started Leaking Underground Storage Tanks – Rem. Started Property Transfer – Form III Investigation started Property Transfer – Form III Remediation Started	Investigation Started  9/14/2015  9/14/2010	R	Started  8/22/2012	Remedial Remedial Started Started Started Started Started Completed
t Upholstery Shop	40 Webster Street	Property Transfer – Form III Investigation started	9/14/2015			
Leopold Green - Greens Autobody	2760 Thru 2786 Main Street	Leaking Underground Storage Tanks – Completed				
Lewtan Industries	103-105 Allyn Street	Leaking Underground Storage Tanks – Rem. Started				
Loomis Armored Inc.	75 Maxim Rd.	Leaking Underground Storage Tanks – Rem. Started				
Loomis Armored Inc.	75 Maxim Road	Property Transfer – Form III				
Lucio Panno	170-172 Roosevelt St	Leaking Underground Storage Tanks – Completed				
M & Z Cleaners / Goodwin Square	225 Asylum Avenue	Property Transfer – Form III Investigation started	2/27/1996			
M. Swift & Sons Inc.	10 Love Lane	Property Transfer – Form III Remediation Started	10/6/2010	8/22	2012	2012
M. Swift & Sons, Inc. Factory (former)	10 Love Lane	Property Transfer – Form III Investigation started	2/2/2018			
M. Swift & Sons, Inc. Factory (former)	10 Love Lane	Property Transfer – Form III Investigation started	2/2/2018			
M. Swift & Sons, Inc. Factory (former)	10 Love Lane	Property Transfer – Form III Investigation started	2/2/2018			
M.d. Fox Building	461 Washington Street	Leaking Underground Storage Tanks – Completed				
M.d.c.	Keaney Street	Leaking Underground Storage Tanks – Completed				
M.I. King Elementary School	25 Ridgefield Street	Leaking Underground Storage Tanks – Investigation	•			

"Hazardous Waste Facilities" as defined by Section 22a-134f of the Connecticut General Statutes

Mccook Hospital	Mccook Hospital	Massachusetts Mutual Life Insurance Company	Mass Mutual Life Insurance	Mary Pafpor	Mary Hooker School	Mary Ellen Oconnor	Market Street Citgo	Mark Twain Apartments	Mark Stephens	Mark Marie	Mark Jay	Marc Sussman	Maranda Builders	Manfred Theide	<u>Name</u>
Vine St.	2 Holcomb St.	140 Garden Street	140 Garden Street	127 Oxford St	200 Sherbrooke Avenue	641 Maple Ave.	410 Market Street	367-381 Farmington Avenue	4 Alwood St	465 Ledyard Rd	56 Kenyon Street	166 Collins Street	450 Windsor Ave.	126 Terry Road	Address
Leaking Underground Storage Tanks – Completed	Leaking Underground Storage Tanks – Investigation	Property Transfer – Form III Remediation Complete	Property Transfer – Form III Investigation started	Leaking Underground Storage Tanks – Completed	Voluntary Remediation: CGS 22a,- 133x	Leaking Underground Storage Tanks – Completed	Site Definition								
		7/5/2006 7/3/2012	1/6/2009												Investigation Remediation Monitoring Remediation Started Started Started Completed
		12 NO													Completed ELUR ELUR Type

"Hazardous Waste Facilities" as defined by Section 22a-134f of the Connecticut General Statutes

#### **TOWN OF: HARTFORD**

	TINZELICES WE SEE Y SE		ACCOUNT OF THE PROPERTY OF THE		<b>.</b>			
TOWN OF: HARTFORD	RTFORD				Remedial Maniforing	Romodiation		
<u>Name</u>	Address	Site Definition	Investigation Started	<u>Started</u>	<u>Started</u>	Completed   ELUR   ELUR Type	ELUR	ELUR Type
Mckinnley-king Vfw #142	2121 Main Street	Leaking Underground Storage Tanks – Pending						
Mdc Hartofr Water Pollution Control Facilty	240 Brainard Road	Leaking Underground Storage Tanks - Completed						
Metal Management - Advo- system, Inc.	239 West Service Road	Property Transfer – Form III Remediation Complete	5/19/2011			9/24/2014	NO	
Metal Management Aerospace, Inc.	239 West Service Road	Property Transfer – Form III Investigation started	10/22/2014					
Metal Management Aerospace, Inc.	239 West Service Road	Property Transfer – Form III Remediation Complete	7/2/2014			4/30/2018	NO	
Michael's Auto Repair (former Sunoco)	1575 Park Street	Leaking Underground Storage Tanks – Rem. Started						
Million Airways	20 Lindberg Dr Brainard Rd	Leaking Underground Storage Tanks – Completed						
Mobil 941 (former Exxon Mobil Station 01-fcq, #12674)	234 Washington Street	Leaking Underground Storage Tanks – Completed						
Mobil Service Station #01-et1 (former)	1157-1161 Albany Avenue	Voluntary Remediation: CGS 22a 133y Remediation Started	'n	8/15/2005				
Mobil Service Station 12674 (01-fc0)	234 Washington Street	Property Transfer – Form III Remediation Started	3/21/2011	3/31/2017				
Mobil Service Station 12677 (01- 037)	519 Farmington Avenue	Property Transfer – Form III Remediation Started	3/21/2011	4/4/2014				
Moore/allen Property	319 Sigourney Street And 325 Sigourney Street	Leaking Underground Storage Tanks – Rem. Started						
Mormon Church	595 Franklin Avenue	Leaking Underground Storage Tanks – Completed						

Mqs Inspections, Inc.

230 Murphy Road

Moses Auto Sales

3400 Main Street

Leaking Underground Storage Tanks – Completed

Property Transfer – Form III Investigation started

2/16/2007

"Hazardous Waste Facilities" as defined by Section 22a-134f of the Connecticut General Statutes

#### TOWN OF HARTFORD

IOWN OF: HARTFORD	ARTFORD				Post			
<u>Name</u>	Address	Site Definition	Investigation Started	<u>Remediation</u> <u>Monitoring</u> <u>Remediation</u> <u>Started</u> <u>Started</u> Completed	Monitoring Started	Remediation Completed	ELUR	ELUR Type
Mr Auto Wash Inc	900 Wethersfield Avenue	Leaking Underground Storage Tanks – Completed						
Mr. D'Italia	141 Kenyon St.	Leaking Underground Storage Tanks – Completed						
Mr. Karliner	150 South Whitney St.	Leaking Underground Storage Tanks – Completed	٠					
Mr. Naurag Agrawal	1414 Asylum	Leaking Underground Storage Tanks – Completed						
Mr. Sparkles Car Washes, Inc (former Paul Ferrulo Property)	279 Washington Street	Leaking Underground Storage Tanks – Completed						
Mr. Tuxedo	137 Sisson Avenue	Property Transfer – Form III Remediation Complete	4/4/2013	10/22/2013		6/25/2019	NO	
Mutual Housing Assoc. Of Hartford	55 Elm Street, Apt. 4a	Leaking Underground Storage Tanks – Investigation						
National Discount Store	769 Park Ave.	Leaking Underground Storage Tanks – Investigation						
National Medical Research Corp.	33 Main Street - 37 Main Street	Leaking Underground Storage Tanks – Completed						
New England Dairy	255 Homestead Avenue	Leaking Underground Storage Tanks – Completed						
New England Dairy	75 Sterling Street	Leaking Underground Storage Tanks – Completed						
New Gate Oil Company	282 Huyshoppe Ave	Leaking Underground Storage Tanks - Completed						
New Park Avenue Auto Repair	385 New Park Avenue	Leaking Underground Storage Tanks - Completed						
New Park Office & Conference Center	151 New Park Avenue	Property Transfer – Form III Investigation started	8/30/2005					

New Park Office & Conference 151 New Park Avenue Center

Property Transfer – Form III Remediation Started

9/26/2008

4/14/2010

"Hazardous Waste Facilities" as defined by Section 22a-134f of the Connecticut General Statutes

Nielsen Hardware Corporation  Nielsen Tool & Die  Northeast Utilities / Fred Richmond  Now Properties & Associates, Llc  Nutmeg International Trucks, Inc Hartford  Addre  Add	Address  453 Ledyard Street  750-770 Wethersfield Ave  770 Wethersfield Avenue  400-410 Sheldon Street  2814 Main Street	Site Definition  Property Transfer – Form III Investigation started  Property Transfer – Form III Investigation started  Property Transfer – Form III Investigation started  Leaking Underground Storage Tanks – Completed  Leaking Underground Storage Tanks – Completed  Property Transfer – Form III	Investigation R Started  11/18/2002  7/21/2010  8/11/2003	<u>Remediation</u> <u>Started</u>	Remedial Monitoring Started	Remediation Completed	<u>  2d   2d   2d   2d   2d   2d   2d   2d</u>
Nielsen Hardware Corporation	750-770 Wethersfield Ave	Investigation started Property Transfer – Form III Investigation started	7/21/2010				
Nielsen Tool & Die	770 Wethersfield Avenue	Property Transfer – Form III Investigation started	8/11/2003				
Northeast Utilities / Fred Richmond	400-410 Sheldon Street	Leaking Underground Storage Tanks – Completed					
Now Properties & Associates, Llo		Leaking Underground Storage Tanks – Completed					
Nutmeg International Trucks, Inc Hartford	130 Brainard Road	Property Transfer – Form III					
Nutmeg International Trucks, Inc Hartford	130 Brainard Road	Property Transfer – Form III				ĸ	c
Office Building	242 Trumbull Street	Property Transfer – Form III Remediation Started	8/11/2003	6/	6/14/2005	14/2005	14/2005
Offices (no Name)	2065 Main Street	Leaking Underground Storage Tanks – Investigation					
Old Em Hart Bldg	393 Homestead Ave	Leaking Underground Storage Tanks – Investigation					
Oliveri Corp.	37 Airport Rd.	Leaking Underground Storage Tanks – Completed					
Our Lady Sorrows Church Corp.	37 Grace St.	Leaking Underground Storage Tanks – Investigation					
Owner	3480 Main Street	Leaking Underground Storage Tanks – Completed					
Parrotta Property	10 Woodside Circle	Leaking Underground Storage Tanks – Rem. Started					
Pat Hensley	740 Prospect Ave	Leaking Underground Storage Tanks - Rem. Started					

"Hazardous Waste Facilities" as defined by Section 22a-134f of the Connecticut General Statutes

#### TOWN OF HADTEODA

TOWN OF: HARTFORD	ARTFORD				<u>Post</u> Remedial				
Name	Address	Site Definition	Investigation Started	n Remediation Started	TWO COLUMN	Remediation Completed	ELUR	ELUR Type	
Patricia Hensley	740 Prospect Avenue	Leaking Underground Storage Tanks – Completed							
Patrick Sign	40 Midland St.	Leaking Underground Storage							

Pro	Pri	Pri	P	PI	(fc ₽	P	P	P	פַ	Р	Р	70	70	70
Prospect Bible Church	Private Residence	Prince Tech (rvts)	Premium Auto, Llc	Plaza Realty	Phoenix Tax Investors, Llc (former Gas Station)	Peter Vouthounes	Perisi Auto	Perez Auto Body (former)	Percy's Auto Body	People's Bank	Paul's Depot Garage	Paul Greenhut	Patrick Sign	Patricia Hensley
576 Prospect Avenue	69 Fenwick St.	500 Brookfield Street	910 New Britain Avenue	15-17 Lincoln St.	127 Nelson Street	240 Farmington Ave.	Garden Street	115 Newfield Avenue	247 Walnut Street	245-749 Farmington Ave.	1115 Capitol Avenue	North Beacon Street	40 Midland St.	740 Prospect Avenue
Leaking Underground Storage Tanks – Completed	Leaking Underground Storage Tanks – Completed	Leaking Underground Storage Tanks – Completed	Property Transfer – Form III Investigation started	Leaking Underground Storage Tanks – Completed	Leaking Underground Storage Tanks – Completed	Leaking Underground Storage Tanks – Completed	Leaking Underground Storage Tanks - Completed	Property Transfer – Form III Investigation started	Leaking Underground Storage Tanks - Completed	Leaking Underground Storage Tanks – Investigation	Leaking Underground Storage Tanks – Completed	Leaking Underground Storage Tanks – Investigation	Leaking Underground Storage Tanks – Completed	Leaking Underground Storage Tanks – Completed
			10/7/2016					4/23/2019						

"Hazardous Waste Facilities" as defined by Section 22a-134f of the Connecticut General Statutes

TOWN OF: HARTFORD	RTFORD		on	Remediation Started	Remedial Monitoring Started	Post Remedial Monitoring Remediation Started Completed	ELUR	ELUR ELUR Type
Name	Address	Site Definition	Started	Startea	1	Completed	BLOW	THE SECTION AND ADDRESS OF THE PARTY OF THE
Public Housing Residents Going Forward, Inc.	1950 Main Street	Voluntary Remediation: CGS 22a 133y Remediation Started		9/15/2004				
R & D Service Center (former Exxon Station)	550 Albany Avenue	Leaking Underground Storage Tanks – Completed						
Racana Aparlment Building	12-16 South St.	Leaking Underground Storage Tanks – Completed						
Ram li, Llo	166 Locust Street	Leaking Underground Storage Tanks – Rem. Started	8					
Ramco Technologies Inc.	281-299 Locust Street	Property Transfer – Form III Remediation Started	2/5/2003	9/16/2013				
Ramon Qurious Park	354 Hudson Street - 380 Hudson Street	Leaking Underground Storage Tanks - Completed						
Ramon Qurious Park	354-380 Hudson Street	Voluntary Remediation: CGS 22a 133x Investigation started	5/4/2011					
Recycling King (former Christie Food & Fuel)	240 Walnut Street	Leaking Underground Storage Tanks - Rem. Started						
Redden Family Llc.	3480 Main Street	Leaking Underground Storage Tanks - Completed						
Reno Auto	525 Franklin Avenue	Leaking Underground Storage Tanks - Rem. Started						
Repair Facility, Former Hartford Motors	43 Hillside Avenue	Leaking Underground Storage Tanks – Completed						
Rh Builders	5355 Nelson Street	Leaking Underground Storage Tanks – Completed						
Richard Bates	164 Oxford St	Leaking Underground Storage Tanks – Completed						
Richard Whitehouse	101 Benton	Leaking Underground Storage Tanks – Completed						
Richard Whitehouse, Horizon Asset Management	221 Laurel Street	Leaking Underground Storage Tanks – Completed						

"Hazardous Waste Facilities" as defined by Section 22a-134f of the Connecticut General Statutes

Name  Richmond Assetts Associates (tower Buisness Associates)  Rics  Rite Aid Pharmacy (cvs)	Address ates 3580 Main St. s) 822 Maple Avenue 1291 Albany Avenue	Site Definition Started  Leaking Underground Storage Tanks - Completed  Leaking Underground Storage Tanks - Rem. Started  Leaking Underground Storage Tanks - Completed
Rite Aid Pharmacy (cvs)	1291 Albany Avenue	Leaking Underground Storage Tanks - Completed
Riverfront Park	600 Leibert Road	Voluntary Remediation: CGS 22a 133x
Robert Black	1800 Albany St.	Leaking Underground Storage Tanks – Completed
Rodger's Wine & Liquor	595 Prospect Ave	Leaking Underground Storage Tanks – Pending
Romano Marble, Granite	330 Ledyard Street	Leaking Underground Storage Tanks – Completed
Rosen Associates	Prospect Ave.	Leaking Underground Storage Tanks – Completed
Rossi Residence	97 Westerly Terrace	Leaking Underground Storage Tanks – Pending
Rourke End	261 Weston Street	Leaking Underground Storage Tanks – Completed
Royal Typewriter	150 New Park Avenue	Property Transfer – Form III
Royal Typewriter	150 New Park Avenue	Property Transfer – Form III
Royal Typewriter Company	150 New Park Avenue	Property Transfer – Form III Investigation started
Royal Typewriter Company	150 New Park Avenue	Property Transfer – Form III Investigation started
Royal Typewriter Company	150 New Park Avenue	Property Transfer – Form III 5/25/2001 Investigation started

"Hazardous Waste Facilities" as defined by Section 22a-134f of the Connecticut General Statutes

TOWN OF: HARTFORD	ARTFORD	Site Definition	Investigation Remediation Started Started	<u>Post</u> <u>Remedial</u> <u>Monitoring</u> <u>Started</u>	Remediation Completed	<u>ELUR</u>	ELUR Type
Name	Address	Site Definition	Investigation Started	1 1	(3.8)	ELUR	ELUR Type
Russ Tires	10 Holmstead Ave.	Leaking Underground Storage Tanks – Pending					
Russo Bros, Inc.	321 West Service Road	Leaking Underground Storage Tanks – Rem. Started					

Sam's Food Store (former Gibbs Oil Company, Circle K # 2703060)	Sam's Food Store #1084	Sam's Food Store #1036 (former Gulf And Circle K 0936)	Salvation Army Storage And Distribution Center	Salvation Army	Sally Taylor	Sal Pritzio	Saint Luke Church	Saint Larewnce Otoole Church	S & C Really	Ryder Truck Rental, Inc.	Ryder Truck Rental #0181a	Ryder Truck Rental
472 Farmington Avenue	675 Wethersfield Avenue	106 Sisson Avenue	333 Homstead Ave.	855 Asuylum Avenue	238 Whitney St.	161-163 Campfield Avenue	66 Bolton Street	494 New Britain Avenue	269 Tower Ave	99 Murphy Road	99 Murphy Road	185 West Service Road
Leaking Underground Storage Tanks – Rem. Started	Leaking Underground Storage Tanks - Rem. Started	Leaking Underground Storage Tanks – Rem. Started	Leaking Underground Storage Tanks – Rem. Started	Leaking Underground Storage Tanks – Completed	Leaking Underground Storage Tanks – Completed	Leaking Underground Storage Tanks – Completed	Leaking Underground Storage Tanks – Pending	Leaking Underground Storage Tanks – Completed	Leaking Underground Storage Tanks – Rem. Started	Voluntary Remediation: CGS 22a 133y Remediation Started	Leaking Underground Storage Tanks – Rem. Started	Leaking Underground Storage Tanks – Completed
	K									10/19/2006		

"Hazardous Waste Facilities" as defined by Section 22a-134f of the Connecticut General Statutes

Shell Facility No. 136323	Shell Facility #136325(frm)	Sharon Landshur	Sfp Real Estate	Select Food Mart, Llc	Scott Musilli	Schindler Elevator	Savmore (former American Eagle)	Sardilli Fruit And Produce Co. Inc.	Sarah Tracey	Sam's Sunoco Store #19	Sam's Food Stores (former Texaco)	Sam's Food Store (former A-1 Gas And Circle-k)	Name	TOWN OF: HARTFORD
510 Farmington Avenue	1620 Park Street	125 Warrington Street	55 Fishfry Street	181 Franklin Avenue	6 Woodside Circle	92 Weston Street	3250 Main Street (intersection With Brainard Road)	212 Locust St.	68 Newton Street	145 New Britain Avenue	611 Maple Avenue	850 Maple Avenue	Address	ARTFORD
Leaking Underground Storage Tanks – Completed	Property Transfer – Form III Remediation Complete	Leaking Underground Storage Tanks – Completed	Property Transfer – Form III Investigation started	Leaking Underground Storage Tanks – Investigation	Leaking Underground Storage Tanks – Completed	Site Definition								
	3/21/2007					8/30/2005							Started	Investigation
	10/6/2011												Started	Remediation
	12/10/2010												Started	Post Remedial Monitoring
	10/20/2016													Remediation
	NO												ELUR	
													Completed ELUR ELUR Type	

Sher's Automotive Center, Inc. 405 Washington Street

Leaking Underground Storage Tanks – Completed Leaking Underground Storage Tanks - Completed

Shell Facility No. 136324

335 Capital Avenue

"Hazardous Waste Facilities" as defined by Section 22a-134f of the Connecticut General Statutes

#### **TOWN OF: HARTFORD**

Starwood Ceruzzi Hartford Llc	St. Francis Hospital	St. Francis Hospital	St Francis Hospital	Southern New England Telephone (former)	Southern Connecticut Gas	Sorenson Lighted Controls	Snet	Snet	Simpson-waverly Elementary School	Sigourney/homestead Redevelopment Project	Short Stop (former Airport Road Autobody)	Name	TOWN OF: HARTFORD
330 New Park Ave	888 Asylum Avenue And 114 Woodland Street	117 Sigourney Street	114 Woodland Street	40 Brainard Road	59 Edwards Street	75 Locust Street	40 Brainard Road	111 Trumbull Street	55 Waverly Street	111 Homestead Avenue-314 Sigourney Street	80 Airport Road	Address	RTFORD
Leaking Underground Storage Tanks - Completed	Leaking Underground Storage Tanks – Investigation	Leaking Underground Storage Tanks – Completed	Leaking Underground Storage Tanks - Completed	Property Transfer – Form III Investigation started	Leaking Underground Storage Tanks – Rem. Started	Leaking Underground Storage Tanks – Completed	Property Transfer – Form III Investigation started	Property Transfer – Form III Investigation started	Leaking Underground Storage Tanks – Completed	Leaking Underground Storage Tanks – Completed	Leaking Underground Storage Tanks – Rem. Started	Site Definition	
				10/23/2018			2/23/2018	3/26/2018				Started Started Completed ELUR Type	$\frac{\underline{Post}}{\underline{Remedial}}$ Investigation Remediation Monitoring Remediation

State Department Of Public Works

505 Hudson Street

Leaking Underground Storage Tanks - Completed

410-474 Capitol Avenue

Leaking Underground Storage Tanks - Completed

State Of Connecticut (former Aetna Life And Casuality Company)

Steve Pepler

93 Amherst Street

Leaking Underground Storage Tanks – Completed

"Hazardous Waste Facilities" as defined by Section 22a-134f of the Connecticut General Statutes

Steven Sobelman  Sticklor Electric Supply Co.  Stratton Apartments  Super Abrasives Laboratory Technology (salt)  Super Stop & Shop Store #634 (former Royal Typenwriter)  Superior Spring & Manufacturing Co. Inc.  T & D Auto Body Service (former	Address  15 Woodside Cir.  225 Walnut Street  502 New Britain Ave.  127 Meadow Street  34-56 Arbor Street  34-56 Arbor Street  350 New Park Avenue  585 Franklin Avenue	Site Definition  Leaking Underground Storage Tanks – Completed  Property Transfer – Form III  Leaking Underground Storage Tanks – Investigation  Leaking Underground Storage Tanks – Investigation  Property Transfer – Form III Investigation started  Leaking Underground Storage Tanks – Rem. Started  Leaking Underground Storage Tanks – Rem. Started  Property Transfer – Form III Investigation started  Leaking Underground Storage Tanks – Rem. Started	Investigation Started  1/26/2005	<u>Started</u>	<u>Monitoring</u> <u>Started</u>	Remediation Completed	ELUR	ELUR Type
Sticklor Electric Supply Co.	225 Walnut Street	Property Transfer – Form III						
Stratton Apartments	502 New Britain Ave.	Leaking Underground Storage Tanks – Investigation	8					
Sun Health	127 Meadow Street	Leaking Underground Storage Tanks – Investigation						
Super Abrasives Laboratory Technology (salt)	34-56 Arbor Street	Property Transfer – Form III Investigation started	1/26/2005					
Super Stop & Shop Store #634 (former Royal Typerwriter)	150 New Park Avenue	Leaking Underground Storage Tanks – Rem. Started						
Superior Spring & Manufacturing Co. Inc.		Property Transfer – Form III Investigation started	2/1/1996					
T & D Auto Body Service (former Gas Station)		Leaking Underground Storage Tanks – Rem. Started						
Taco Bell (former Atlas Texaco)	255 Farmington Avenue	Leaking Underground Storage Tanks – Completed						
Tdp Automotive (pittmans Property)	3054 Main Street	Leaking Underground Storage Tanks – Completed						
Texaco Station	20 Webster Street & 611 Maple Avenue	Property Transfer – Form III						
The Associated Construction Company (former Gas Station)	1000 Wethersfield Avenue To 1010 Wethersfield Avenue	Leaking Underground Storage Tanks – Completed						
The Hartford Courant Company	121 Wawarme Avenue	Property Transfer – Form III Remediation Started	10/22/2014	12/30/2016				
The Hartford Courant Company	285-305 Broad Street	Property Transfer - Form III Post Remedial Monitoring Started	10/1/1997		9/1/2008		NO	
The Hartford Courant Company	285-305 Broad Street	Property Transfer – Form IV Remediation Complete	12/17/2013			10/23/2018	NO	

"Hazardous Waste Facilities" as defined by Section 22a-134f of the Connecticut General Statutes

**TOWN OF: HARTFORD** Name Site Definition <u>Post</u>
<u>Remedial</u>

<u>Investigation Remediation Monitoring Remediation</u>
<u>Started Started Started Completed ELUR Type</u>

The Hartford Plaza (national Car Rental)	598 Asylum Street To 600 Asylum Street	Leaking Underground Storage Tanks - Completed	
The Hollander Building (former410 Asylum Limited Partership)	410 Asylum Street	Leaking Underground Storage Tanks - Completed	
The Master Detailing Specialist, Llc (former Lombardo's Service Center)	446 Franklin Avenue	Leaking Underground Storage Tanks – Completed	
The Mcgovern Granite Company (former Exxon Station #3-5159)	432 Fairfield Avenue	Leaking Underground Storage Tanks – Rem. Started	
The Salvation Army	333 Homestead Avenue	Leaking Underground Storage Tanks – Completed	
The Sticklor Electric Co.	225 Walnut Street	Leaking Underground Storage Tanks - Completed	
Thomas Cadillac, Inc. Facility	170 Weston Street	Property Transfer – Form III Investigation started	8/8/2011
Thomas Cadillac, Inc. Facility	170 Weston Street	Property Transfer – Form III Investigation started	8/8/2011
Thomas Mesmore	1090 Prospect Ave	Leaking Underground Storage Tanks – Completed	
Thomas Raftery Inc.	1055 Broad Street	Leaking Underground Storage Tanks – Investigation	
Tires Plus Wheels Former Holiday Drive In Cleaners	888 Wethersfield Avenue	Property Transfer – Form III Investigation started	10/3/2014
Tom Cantone	58 Adalane Road	Leaking Underground Storage Tanks – Completed	
Tony March Buick Dealership (former)	77 Leibert Road	Property Transfer – Form III Investigation started	7/12/2011
Tony Marsh Buick	7726 Wethersfield Ave.	Leaking Underground Storage Tanks – Investigation	

"Hazardous Waste Facilities" as defined by Section 22a-134f of the Connecticut General Statutes

TOWN OF: HARTFORD	ARTFORD	RTFORD  Investigation Remea	Connection Connection	Connecticut General Statutes <u>Post</u> <u>Remedial</u> <u>iation Monitoring Remediation</u>	911
<u>Name</u>	Address	Site Definition	Started	Started Complete	Completed ELUR ELUR Type
Town & Country Club	22 Woodland Avenue	Leaking Underground Storage Tanks – Completed			
Tri-mount Cleaners	9 & 11 Wyllys St & 1,3,5 & 7 Wethersfield Avenue	Property Transfer – Form III			
Tri-mount Cleaners	9 & 11 Wyllys St & 1,3,5 & 7 Wethersfield Avenue	Property Transfer – Form III Investigation started	9/16/2015		
Tri-mount Cleaners	9 & 11 Wyllys St & 1,3,5,7 Wethersfield Avenue	Property Transfer – Form III Investigation started	9/24/2007		
Trinity College	300 Summit Street (broad Street And Crescent Street)	Leaking Underground Storage Tanks – Completed			
Trinity Sunoco (former Circle K #84631)	1344 Broad Street	Leaking Underground Storage Tanks – Completed			
Trumbull On The Park Assosiates	40 Trumbull Street	Leaking Underground Storage Tanks – Rem. Started	Ti.		
Tucker Mechanical - Division Of Emcor	189 Maxim Road	Property Transfer – Form III Remediation Complete	2/2/2007	5/5/2015	NO
U.s. Postal Service	189 Washington Street	Leaking Underground Storage Tanks – Completed			
U.s. Postal Service	70 Weston St.	Leaking Underground Storage Tanks – Completed			
U.s. Postal Service Hartford Vmf	85 Weston Street	Leaking Underground Storage Tanks Pending			
Udolf Property	258 South Whitney Street	Leaking Underground Storage Tanks – Pending			
Udolf Property (former Texaco Station)	258 South Whitney Street	Leaking Underground Storage Tanks - Rem. Started			
U-haul	3197 Main St.	Leaking Underground Storage Tanks - Completed			
Uicerueruff Residence	56 Bloomfield Rd.	Leaking Underground Storage Tanks - Completed			

#### Thursday, January 14, 2021

# List of Contaminated or Potentially Contaminated Sites

"Hazardous Waste Facilities" as defined by Section 22a-134f of the Connecticut General Statutes

Name			
Address			
Site Definition			
Started	Investigation		
Started	Remediation		
Started	n Monitoring	Remedial	
Completed	Remediation		
ELUR			
ELUR Type			

										is.				
Veeder-root Company	Veeder-root Company	Valero Branded Station	Vacant Lot (proposed Police Sub-station)	Vacant Building	Vacant	Vacant	Unknown	Unknown	Unknown	Unknown	Univ.of Htfd.(htfd.col.women)	United Truck Leasing Corp.	United Parcel Service	Unfried Residents
70 Sargeant Street	28 Sargeant Street	215 Albany Avenue	134 Affleck Street	464 Washington Street	481-487 Park Street	189-495 Park St.	75 Pratt St.	500 Blue Hills Avenue	159 Westland St.	149 Holcomb	1365 Asylum Ave	265 Murphy Road	90 Locust Street	67 Kenyen
Property Transfer – Form III	Property Transfer – Form III	Leaking Underground Storage Tanks – Completed	Leaking Underground Storage Tanks – Completed	Leaking Underground Storage Tanks – Rem. Started	Leaking Underground Storage Tanks – Completed	Leaking Underground Storage Tanks Completed	Leaking Underground Storage Tanks – Completed	Leaking Underground Storage Tanks – Completed						

"Hazardous Waste Facilities" as defined by Section 22a-134f of the Connecticut General Statutes

TOWN OF: HARTFORD	ARTFORD						
<u>Name</u>	Address	Site Definition	Investigation Started	<u>Remediation</u> <u>Started</u>	Monitoring Remediation Started Completed	ELUR	<u>Completed</u> <u>ELUR</u> <u>ELUR Type</u>
Walnut Huntley, Llc	41 Walnut Street	Leaking Underground Storage Tanks – Completed					
Walter & Robin Orlander	212 Laurel St.	Leaking Underground Storage Tanks – Completed					
Walter Petry	1047 Maple Ave.	Leaking Underground Storage Tanks – Completed					
Walton Auto Repair Shop (former)	127 Nelson Street	Property Transfer – Form III Investigation started	1/9/2015				
Watkinson School	180 Bloomfield Ave.	Leaking Underground Storage Tanks – Completed					
We Clean Dry Cleaners	233 Capen Street	Property Transfer – Form III Investigation started	10/7/2016				
Webster School, Noah	5 Cone Street	Leaking Underground Storage Tanks – Rem. Started					
West Middle School	927 Asylum Avenue	Leaking Underground Storage Tanks – Completed					
Westbrook Village Hartford	22 Mark Twain Drive	Voluntary Remediation: CGS 22a 133x Investigation started	7/25/2019	5/29/2019			
Westbrook Village Hartford	22 Mark Twain Drive	Voluntary Remediation: CGS 22a 133x Remediation Started	7/25/2019	5/29/2019			
Western Pacific	51 - 99a Homestead Avenue	Property Transfer – Form III					
Westland Apartments	165 Westland St.	Leaking Underground Storage Tanks - Completed					
Weston Street Mobil (former Gentle Touch Carwash Mobil)	140 Weston Street	Leaking Underground Storage Tanks – Completed					
Weston Street Sunoco (former Mobil Station)	125 Weston Street	Leaking Underground Storage Tanks – Rem. Started					
Westone Residence	158 North Prospect St.	Leaking Underground Storage Tanks - Completed					

"Hazardous Waste Facilities" as defined by Section 22a-134f of the Connecticut General Statutes

0
Š
$\Rightarrow$
_
0
П
工
70
I
0
70

<u>Post</u> Remedial

Address		
Site Definition		
Started	Investigation	
<u>Started</u>	Remediation	
Started	Monitoring	Welliemini
Completed	Remediation	
ELUR		
ELUR Type		

Whitey's Towing (former Eastern 305 West Service Road Fence Co. And Yale Transport) Site Definition

Whitney Chain/dresser Industries 237-245 Hamilton Street

Leaking Underground Storage Tanks – Rem. Started

Property Transfer – Form III Investigation started

1/17/2019

Leaking Underground Storage Tanks – Completed

Wt Apartments Of Hartford

12 Willard Street

110 Walnut Street And 112 Walnut Street

Leaking Underground Storage Tanks – Completed

Winifred Bennet